



**Ruapehu District Council**  
RB292 Mangateitei Road Rail Overbridge  
Detailed Investigation and Posting Evaluation

April 2021



# Table of contents

1.	Summary .....	4
2.	Introduction.....	4
2.1	Background.....	4
2.2	Scope and limitations .....	5
2.3	Site Investigation.....	6
3.	Posting Evaluation .....	10
2.4	Material Strengths.....	10
2.5	Section Capacity .....	10
2.6	Loadings and Load Factors .....	10
2.7	Posting Evaluation Results.....	11
4.	Discussion and Conclusion .....	11
5.	Recommendations .....	11

## Appendices

Appendix A - (Rating and Posting Calculations)

Appendix B - (Bridge Inspection Reports)

# 1. Summary

The Mangateitei Rail Overbridge is one of Ruapehu District Council (RDC) bridges inspected by GHD as part of the routine bridge inspection. During the inspection, it was observed that the bridge has deteriorated further, and we suspected that the bridge capacity for vehicular loadings may be less than the posted load limits. GHD carried out a live load assessment to confirm the bridge live load capacity.

Based on the results of our assessment, we conclude that the bridge has a live load capacity less than the existing posted limit with an Allowable Axle Load of 6000kg and posting "GROSS" of 60% of Class 1. (Currently 70% Class 1 with no axles limits). Both have a speed restriction for HCVs.

Due to the issues found, replacing the bridge is recommended as the existing bridge is all timber and not feasible to strengthen.

We recommend the following:

- Yearly inspections of the bridge to assess decay and deterioration.
- Update the posted limit on the bridge (as per the reassessment) within 1 month.

# 2. Introduction

## 2.1 Background

The Mangateitei Rail Overbridge was first constructed in 1908 by the NZ Government Railways (Kiwirail Bridge ID 163) and became a local road asset in the 1980s. The bridge is located along Mangateitei Road, Ohakune. Refer to Figure 1 below. It has a total length of about 17.4m consisting of three spans of which two 5.3m long simply supported end spans and a 5.4m central simply supported span. Each span comprises 6 timber beams supporting flat timbers and running boards. The deck spans are supported on reinforced concrete abutments and timber piers, which are, in turn, supported on concrete foundations.

The bridge has a carriageway width of 4.2m and carries one lane of traffic over a single rail track and an access track.

The bridge is currently posted at 70% of Class 1 and a speed restriction of 15 km/h. Axle weights are not posted.

The bridge provides road access to farms, vegetable growers and forestry with associated heavy vehicles. Due to the heavy vehicles using the bridge which could be more than the posted limit, it was observed that the bridge has started to deteriorate.

This report presents our assessment methodology, findings, and recommendation for the bridge.





**Figure 1 Mangateitei Rail Overbridge Locality Plan**

## **2.2 Scope and limitations**

*This report has been prepared by GHD for Ruapehu District Council and may only be used and relied on by Ruapehu District Council for the purpose agreed between GHD and the Ruapehu District Council as set out in Section 2.2 of this report.*

*GHD otherwise disclaims responsibility to any person other than for Ruapehu District Council arising in connection with this report. GHD also excludes implied warranties and conditions, to the extent legally permissible.*

*The services undertaken by GHD in connection with preparing this report were limited to those specifically detailed in the report and are subject to the scope limitations set out in the report.*

*The opinions, conclusions and any recommendations in this report are based on conditions encountered and information reviewed at the date of preparation of the report. GHD has no responsibility or obligation to update this report to account for events or changes occurring subsequent to the date that the report was prepared.*

*The opinions, conclusions and any recommendations in this report are based on assumptions made by GHD described in this report. GHD disclaims liability arising from any of the assumptions being incorrect.*

*GHD has prepared this report on the basis of information provided by Ruapehu District Council and others who provided information to GHD (including Government authorities)], which GHD has not independently verified or checked beyond the agreed scope of work. GHD does not accept liability in connection with such unverified information, including errors and omissions in the report which were caused by errors or omissions in that information.*

*This report excludes seismic and scour assessment and excludes a full condition report*

## 2.3 Site Investigation

In March 2021, GHD Ltd carried out a Principal inspection on the bridge as per the bridge inspection program. The Principal Inspection is carried out on the bridge asset by rotation over six years and a general inspection is carried out every two years. These are programmed for annual completion by June each year. This is to determine the condition of the bridge and to report on defects of the bridge.

### 3.3.1 Measured Dimensions

The timber deck planks were measured to have a width of 200mm and depth of 100mm.

Only the timber stringers at spans 1 and 3 were observed in detail (in closeup). Measurements were recorded at Span 3 (North-East) as this has the best access to the main stringers at midspan as shown in Figure 2 below. The central span is not readily accessible and permission from Kiwirail is required as there are electrical cables below the deck.

The actual dimensions recorded for the timber stringers at Span 3 are shown in Table 1 below. The timber stringers 1 and 6 (edge beams) are located on the Eastern and Western end respectively.

**Table 1 Timber Stringers Dimensions**

Timber Stringers	Depth (mm)	Width (mm)
Stringer No. 1	330	230
Stringer No. 2	350	230
Stringer No. 3	340	220
Stringer No. 4	340	245
Stringer No. 5	360	255
Stringer No. 6	344	237

### 3.3.2 Bridge Condition


The following were observed on the bridge:

- significant wear on the running planks;
- deck planks are between fair and deteriorating condition;
- stringers are between deteriorating & seriously deteriorating (i.e. with cracks and some decay);
- crossheads/crossbeams have some longitudinal cracks; and
- piers have some deterioration (i.e., with cracks and some decay) which has been repaired in some places.

The stringers have deterioration as cracking and timber decay are primarily recorded on them. At Span 3; timber stringers No. 3 and 4 were recorded as the most deteriorated with cracks and timber decay.

On both faces of Stringer No. 3, a longitudinal crack of approximately 1 m long and 18 mm deep was observed roughly at 1.7 m from the Abutment support and about 150 mm from the top of the stringer. Also, extensive cracking was observed in the soffit, with variable depths and lengths. Refer to Figure 3 below.

On both faces of Stringer No. 4, a longitudinal crack of approximately 0.8 m long and 36 mm deep was observed roughly at 1.9 m from the Abutment support and about 200 mm from the top of the stringer. Refer to Figure 4 below.



**Figure 2 Deck Soffit Span 3 (North-East)**





**Figure 3 Timber Stringer No. 3 Defects**





**Figure 4 Timber Stringer No. 4 Defects**

## 3. Posting Evaluation

Posting evaluations were carried out per Section 7 of the NZ Transport Agency Bridge Manual 3<sup>rd</sup> Edition and NZS 3603:1993.

### 2.4 Material Strengths

The timber properties used in the assessment were taken from NZS 3603 Table 2.2 for the timber deck planks and AS 1720.1 Table H2.1 for the timber stringers:

Timber deck planks (assuming radiata pine, no 1 framing):

- Density,  $\gamma_{td}$ : 550 kg/m<sup>3</sup>
- Bending strength,  $f_b$ : 10 MPa
- Shear strength  $f_s$ : 3.8 MPa
- Compression parallel to grain,  $f_c$ : 15 MPa
- Modulus of elasticity, E: 6 GPa

Timber stringers (assuming F8 for gum, red):

- Density,  $\gamma_{ts}$ : 900 kg/m<sup>3</sup>
- Bending strength,  $f_b$ : 22 MPa
- Shear strength  $f_s$ : 2.2 MPa
- Compression parallel to grain,  $f_c$ : 18 MPa
- Modulus of elasticity, E: 9.1 GPa

### 2.5 Section Capacity

Section capacities of the deck planks and stringers were determined from NZS 3603.

A material strength reduction factor of 0.8 was adopted.

A condition factor of 0.85 was applied to the strength reduction factor for the deck (assuming the deck is in fair to deteriorated condition) and a 0.9 condition factor was applied to the strength reduction factor for the stringers (assuming the stringer is in deteriorated condition).

### 2.6 Loadings and Load Factors

#### 3.6.1 Dead Load

The dead load for the superstructure was determined assuming the unit weight of the stringers of 8.8kN/m<sup>3</sup> for red gum (seasoned) timber and for the deck planks 5.39kN/m<sup>3</sup> for radiata pine timber. The load factor for the dead load was taken as 1.25 per Table 7.4 of the Bridge Manual.

#### 3.6.2 Vehicle Live Load

The stringers and deck plank were assessed as per Sections 7.4 and 7.5 of the Bridge Manual respectively and using the appropriate loading for Posting evaluation.

The load factor for traffic load was taken as 1.9.

A dynamic load factor of 1.1 was adopted (assuming the bridge has a speed restriction of 10 km/h).



## **2.7 Posting Evaluation Results**

Results of the assessment are shown below:

### **3.7.1 Timber Deck Plank**

Allowable axle load (AAL): 6000 kg

### **3.7.2 Timber Stringers**

Posting "GROSS" for flexure: 60% Class 1 (governs)

Posting "GROSS" for shear: 160% Class 1

Refer to Appendix A for calculations.

## **4. Discussion and Conclusion**

The above result for the stringers was determined using a grillage analysis: one stringer carries a maximum of 50% of one wheel load, with the load shared by the other stringers.

Based on the above, we conclude that the Posting "GROSS" will be 60% Class 1 with a 10 kph speed restriction.

From the investigation conducted, replacing the bridge is recommended, as the existing bridge is all comprised of timber and repairing or replacing the timbers is not recommended. The only way forward by maintaining the existing bridge is to replace individual elements and to keep it a three-span bridge which will be more expensive, where the new piers will require pier protection works, and the level of the road will need to be raised at least another 1 metre to meet Kiwirail clearances. This clearance requirement is similar for both renewal and replacing of elements.

## **5. Recommendations**

We recommend the following:

- Ongoing assessment required at the bridge yearly to determine the extent and if deteriorating further;
- update the posted load and speed limit on the bridge within 1 month (as per the reassessment)

# Appendices



# **Appendix A - (Rating and Posting Calculations)**



**GHD LIMITED**



**BRIDGE CAPACITY DESIGN CHECK**

**CLIENT:**

**BRIDGE NAME OR NUMBER:** B292 -- Mangateitei Rail Bridge

**BRIDGE LOCATION OR ROAD:** Mangateitei Road, Ohakune

**DESIGN SATISFACTORY FOR:**

AXLES : 6,000 kg

GROSS: 60 % Class 1

SPEED: 10 kph

**LIMITING BRIDGE COMPONENT:**

Posting evaluations were carried out per Section 7 of the NZ Transport Agency Bridge Manual 3rd Edition and NZS 3603:1993.

Timber stringers sized used: avg.depth (d) = 340 mm and avg.width (w) = 230 mm  
The above result for the stringers was analysed resulting two stringer will resist one wheel loading (i.e. the vehicle is central to the bridge and the wheel is between the stringers).  
The timber properties used in the assessment were taken from AS 1720.1 Table H2.1 (assuming F8 for gum, red) and are as follows:

- Bending strength, fb: 22 MPa
- Shear strengthfs: 2.2 MPa
- Compression parallel to grain, fp: 18 MPa
- Modulus of elasticity, E:9.1 GPa

Section capacities of the deck planks and stringers were determined from NZS 3603. A material strength reduction factor of 0.8 was adopted.  
A condition factor of 0.85 was applied to the strength reduction factor for the deck (assuming the deck is in fair to deteriorated condition) and a 0.85 condition factor was applied to the strength reduction factor for the stringers (assuming the stringer is in seriously deteriorated condition).

**SIGNED:**

**DATE:** 29/04/2021

Chartered Professional Engineer: Alex Chisholm

Member ID 194760



# Calculations

GHD Limited

CLIENT: Ruapehu District Council	JOB No:	SHEET:
JOB: Mangateitei Rail Overbridge Assessment	CALCS By: RT	DATE: 19 April 2021
SUBJECT: Determination of dead load and demands	CHECKED By:	DATE:

Description	Notation	Value	Units	Comment
density of timber (deck)	$\gamma_{td}$	5.39	kN/m <sup>3</sup>	<i>assume radiata pine (550 kg/m<sup>3</sup>) assume F8 (gum, red &amp; seasoned)</i>
density of timber (stringer)	$\gamma_{ts}$	8.83	kN/m <sup>3</sup>	<i>(900 kg/m<sup>3</sup>) tributary width</i>
triburaty width per beam	$b_{rp}$	850	mm	<i>0.5 x (900+800)</i>
<b>running planks</b>				
thickness	$t_{rp}$	50	mm	
weight of running planks	$w_{rp}$	0.23	kN/m	<i>effect for one beam</i>
<b>deck</b>				
thickness	$t_{deck}$	100	mm	
weight of deck	$w_{deck}$	0.46	kN/m	<i>effect for one beam</i>
<b>timber beams</b>				
width	$b$	255	mm	<i>maximum</i>
depth	$d$	360	mm	<i>maximum</i>
weight of beam	$w_b$	0.81	kN/m	
<b>railings</b>				
	$w_r$	0.50	kN/m	<i>assumed per side</i>
<b>uniform dead load on one beam</b>	$w_b$	1.50	kN/m	
<b>span length</b>	$L$	5.40	m	
<b>moment demand due to dead load for beam</b>	$M^*_{DL}$	5.5	kN-m	$M^*_{DL} = w_b L^2 / 8$
<b>shear demand due to dead load for beam</b>	$V^*_{DL}$	4.0	kN	$V^*_{DL} = w_b L / 2$



# Calculations

GHD Limited

CLIENT: Ruapehu District Council	JOB No:	SHEET:
JOB: Mangateitei Rail Overbridge Assessment	CALCS By: RT	DATE: 19 April 2021
SUBJECT: Determination of deck plank capacity	CHECKED By:	DATE:

Description	Notation	Value	Units	Comment
distance between supports	$L_B$	900	mm	<i>maximum distance between beams</i>
depth of a member in direction of flexural loading	$d$	100	mm	
breadth of a member perpendicular to direction of flexural loading	$b$	200	mm	<i>for planks laid flat, with running planks at least 50mm</i>
nominal width	$b_n$	650	mm	$b_n = 250 + 2 \times 200$
centre to centre spacing of members	$s$	200	mm	
distance between points of restraint against lateral movements of the compression edge	$L_{ay}$	300	mm	<i>assume width of running planks</i>
<b><i>bending capacity</i></b>				
load duration factor	$k_1$	0.8		<i>NZS 3603:1993 Table 2.4 (duration of load taken as medium)</i>
parallel support factor	$k_4$	1.20		<i>NZS 3603:1993 Table 2.7 (assume 3 elements with same deformation)</i>
grid system factor	$k_5$	1.11		$k_5 = 1 + (k_4 - 1) (1 - 2s / L_B)$ <i>but not less than 1.0</i>
slenderness coefficient	$S$	5.93		$S = 1.35 [L_{ay} / b [(d/b)^2 - 1]^{0.5}]^{0.5}$
stability factor	$k_8$	1.00		<i>moisture condition dry</i>
characteristic extreme fibre stress in bending parallel to the grain	$f_b$	10.0	MPa	<i>assume radiata pine</i>
section modulus	$Z$	1083333	mm <sup>3</sup>	$Z = b_n d^2 / 6$
nominal bending strength	$M_{no}$	11.6	kN-m	$M_{no} = k_1 k_4 k_5 k_8 f_b Z$ <i>may be increased by 25% as per Section 7.5.5 a. of BM</i>
capacity factor	CF	1.25		
nominal bending strength	$M_n$	14.4	kN-m	$M_n = M_{no} \times CF$
<b><i>shear capacity</i></b>				
characteristic shear stress	$f_s$	3.8	MPa	<i>assume radiata pine</i>
shear plane area	$A_s$	43333	mm <sup>2</sup>	$A_s = 2 b_n d / 3$
nominal shear strength	$V_n$	175.6	kN	$V_n = k_1 k_4 k_5 f_s A_s$

References: Bridge Manual and NZS 3603





# Calculations

GHD Limited

CLIENT: Ruapehu District Council	JOB No:	SHEET:
JOB: Mangateitei Rail Overbridge Assessment	CALCS By: RT	DATE: 19 April 2021
SUBJECT: Determination of stringer capacity	CHECKED By:	DATE:

Description	Notation	Value	Units	Comment
distance between supports	$L_B$	5400	mm	
depth of a member in direction of flexural loading	$d$	340	mm	
breadth of a member perpendicular to direction of flexural loading	$b$	220	mm	
centre to centre spacing of the supporting members	$s$	800	mm	
distance between points of restraint against lateral movements of the compression edge	$L_{ay}$	200	mm	
<b><i>bending capacity</i></b>				
load duration factor	$k_1$	0.8		<i>NZS 3603:1993 Table 2.4 (duration of load taken as medium)</i>
parallel support factor	$k_4$	1.00		$k_5 = 1 + (k_4 - 1) (1 - 2s / L_B)$
grid system factor	$k_5$	1.00		<i>but not less than 1.0</i>
slenderness coefficient	$S$	1.40		$S = 1.35 [L_{ay} / b [(d/b)^2 - 1]^{0.5}]^{0.5}$
stability factor	$k_8$	1.00		<i>moisture condition dry</i>
characteristic extreme fibre stress in bending parallel to the grain	$f_b$	22.0	MPa	<i>assumed F8 (gum, red &amp; seasoned)</i>
section modulus	$Z$	4238667	mm <sup>3</sup>	$Z = b d^2 / 6$
nominal bending strength	$M_n$	74.6	kN-m	$M_n = k_1 k_4 k_5 k_8 f_b Z$
<b><i>shear capacity</i></b>				
characteristic shear stress	$f_s$	2.2	MPa	<i>assumed F8 (gum, red &amp; seasoned)</i>
shear plane area	$A_s$	49867	mm <sup>2</sup>	$A_s = 2 b d / 3$
nominal shear strength	$V_n$	87.8	kN	$V_n = k_1 k_4 k_5 f_s A_s$

References: AS 17201.1 and NZS3603

Deck rating load

Axle 190 kN

per wheel 95 kN

load contact area 900 x

nominal plank width

UDL

600 mm


650 mm

105.56 kN/m

Table 7.7 BM

HO Alternative (b)

<https://beamguru.com/online/beam-calculator/?save=6cf07013d1981650b3af295dea60765f>



Deck Posting/50MAX evaluation load


Axle 80 kN  
 per wheel 40 kN  
 load contact area 500 x  
 nominal plank width 200 mm  
 UDL 80.00 kN/m

Table 7.8 BM

HN

200 mm  
 650 mm  
 80.00 kN/m

<https://beamguru.com/online/beam-calculator/?save=6ff268235430f1ffa2b24f2eef652f61>



Beam Live Load from Grillage Analysis

M\*

	Axle			UDL			
Posting	102	beam 1	11.03	8.01%	8.925	11.03	
	138	beam 2	29.14	21.16%	32.53	8.13	37.27
		beam 3	26.85	19.50%		8.13	34.98
		beam 4	29.59	21.49%		8.13	<b>37.72</b>
		beam 5	18.31	13.30%		8.13	26.44
		beam 6	-2.07	-1.50%			-2.07
				<b>112.85</b>		<b>81.95%</b>	

Rating	204	beam 1	22.06	8.01%	8.925	22.06	
	275	beam 2	58.28	21.16%	32.53	8.13	66.41
		beam 3	53.7	19.50%		8.13	61.83
		beam 4	59.18	21.49%		8.13	<b>67.31</b>
		beam 5	36.62	13.30%		8.13	44.75
		beam 6	-4.14	-1.50%			-4.14
				<b>225.7</b>			


V\*

	Axle			UDL			
Posting	102	beam 1	4.08	8.00%	48.195	4.08	
	51	beam 2	10.79	21.16%	24.10	6.02	16.81
		beam 3	9.94	19.49%		6.02	15.96
		beam 4	10.96	21.49%		6.02	<b>16.98</b>
		beam 5	6.78	13.29%		6.02	12.80
		beam 6	-0.77	-1.51%			-0.77
				<b>41.78</b>		<b>81.92%</b>	

Rating	204	beam 1	8.16	8.00%	48.195	8.16	
	102	beam 2	21.58	21.16%	24.10	6.02	27.60
		beam 3	19.88	19.49%		6.02	25.90
		beam 4	21.92	21.49%		6.02	<b>27.94</b>
		beam 5	13.56	13.29%		6.02	19.58
		beam 6	-1.54	-1.51%			-1.54
				<b>83.56</b>			

**Robot Grillage Analysis - Bending Moment Results of Stringers:**

(2 x 60 kN wheel loads applied at mid span with one wheel load directly over stringer 2 to compare moment distribution)





# Calculations

GHD Limited

CLIENT: Ruapehu District Council	JOB No:	SHEET:
JOB: Mangateitei Rail Overbridge Assessment	CALCS By: RT	DATE: 19 April 2021
SUBJECT: Results for deck	CHECKED By:	DATE:

Description	Notation	Value	Units	Comment
<b>flexure</b>				
nominal moment capacity	$R_i$	14.4	kN-m	
material strength factor	$\phi_D$	<b>0.80</b>		<i>NZS 3603</i>
condition factor	CF	<b>0.85</b>		<i>between good or fair and deteriorated</i>
strength reduction factor	$\phi$	0.68		$\phi = CF \phi_D$
dead load factor	$\gamma_D$	<b>1.25</b>		
overload factor	$\gamma_O$	<b>1.49</b>		
live load factor	$\gamma_L$	<b>1.9</b>		
dead load effect	DL	<b>0.00</b>	kN-m	<i>dead load may be neglected Section 7.5.5 a of BM</i>
deck rating load	DRL	<b>10.7</b>	kN-m	<i>from deck live load demands</i>
deck posting/50MAX evaluation load	DPL	<b>6.5</b>	kN-m	<i>from deck live load demands</i>
with speed restriction? (yes/no)		<b>yes</b>		
speed limit (30/10)		<b>10</b>		
dynamic factor	I	<b>1.3</b>		
corrected dynamic factor	$I_M$	1.10		
overload capacity of nominal width	$R_O$	6.6	kN-m	$R_O = (\phi R_i - \gamma_D DL) / \gamma_O$
Rating load effect	RLE	11.7	kN-m	$RLE = DRL \times I$
Deck capacity factor	<b>DCF</b>	<b>0.56</b>		$DCF = R_O / RLE$
live load capacity of nominal width	$R_L$	5.2	kN-m	$R_L = (\phi R_i - \gamma_D DL) / \gamma_L$
Posting (or 50MAX) load effect	PLE	7.1	kN-m	$PLE = DPL \times I$
Allowable axle load	<b>AAL</b>	<b>6000</b>	<b>kg</b>	$AAL = R_L / PLE \times 8200$
<b>shear</b>				
nominal moment capacity	$R_i$	175.6	kN	
material strength factor	$\phi_D$	0.80		
condition factor	CF	0.85		
strength reduction factor	$\phi$	0.68		$\phi = CF \phi_D$
dead load factor	$\gamma_D$	<b>1.25</b>		
overload factor	$\gamma_O$	<b>1.49</b>		
live load factor	$\gamma_L$	<b>1.9</b>		
dead load effect	DL	<b>0.00</b>	kN	<i>dead load may be neglected Section 7.5.5 a of BM</i>
deck rating load	DRL	<b>47.5</b>	kN	<i>from deck live load demands</i>
deck posting/50MAX evaluation load	DPL	<b>20.0</b>	kN	<i>from deck live load demands</i>
dynamic factor	I	1.10		
overload capacity of nominal width	$R_O$	80	kN	$R_O = (\phi R_i - \gamma_D DL) / \gamma_O$
Rating load effect	RLE	52	kN	$RLE = DRL \times I$
Deck capacity factor	<b>DCF</b>	<b>1.54</b>		$DCF = R_O / RLE$
live load capacity of nominal width	$R_L$	63	kN	$R_L = (\phi R_i - \gamma_D DL) / \gamma_L$
Posting (or 50MAX) load effect	PLE	22	kN	$PLE = DPL \times I$
Allowable axle load	<b>AAL</b>	<b>23500</b>	<b>kg</b>	$AAL = R_L / PLE \times 8200$



# Calculations

GHD Limited

CLIENT: Ruapehu District Council	JOB No:	SHEET:
JOB: Mangateitei Rail Overbridge Assessment	CALCS By: RT	DATE: 19 April 2021
SUBJECT: Results for stringers	CHECKED By:	DATE:

Description	Notation	Value	Units	Comment
<b>flexure</b>				
span length	S	5.4	m	
nominal moment capacity	$R_i$	74.6	kN-m	refer "stringer capacity" tab
material strength factor	$\phi_D$	0.80		NZS 3603
condition factor	CF	0.90		assume deteriorated
strength reduction factor	$\phi$	0.72		
dead load factor	$\gamma_D$	1.25		
overload factor	$\gamma_O$	1.49		
live load factor	$\gamma_L$	1.9		
eccentricity	e	1.00		
dead load effect	DL	5.5	kN-m	from dead load demands
rating load	0.85 HO	67.0	kN-m	from stringer LL demands
posting load	0.85 HN	38.0	kN-m	from stringer LL demands
with speed restriction? (yes/no)		yes		
speed limit (30/10)		10		
dynamic factor	$I_{M_o}$	1.30		$I_{M_o} = 1 + (15 / (S + 38))$ with speed restriction for 30 km/h:
				$I_M = (I_{M_o} - 1) \times 0.67 + 1$ for 10 km/h:
corrected dynamic factor	$I_M$	1.10		$I_M = (I_{M_o} - 1) \times 0.33 + 1$
overload capacity	$R_O$	31	kN-m	$R_O = (\phi R_i - \gamma_D DL) / \gamma_O$
Rating load effect	RLE	74	kN-m	$RLE = 0.85HO \times I_M \times e$
Rating CLASS	<b>CLASS</b>	<b>43%</b>		$CLASS = R_O / RLE$
live load capacity	$R_L$	25	kN-m	$R_L = (\phi R_i - \gamma_D DL) / \gamma_L$
Posting load effect	PLE	42	kN-m	$PLE = 0.85HN \times I_M \times e$
Posting GROSS	<b>GROSS</b>	<b>59%</b>		$GROSS = R_L / PLE$





# Calculations

GHD Limited

CLIENT: Ruapehu District Council	JOB No:	SHEET:
JOB: Mangateitei Rail Overbridge Assessment	CALCS By: RT	DATE: 19 April 2021
SUBJECT: Results for stringers	CHECKED By:	DATE:

Description	Notation	Value	Units	Comment
<b>shear</b>				
nominal moment capacity	$R_i$	87.8	kN	refer "stringer capacity" tab
material strength factor	$\phi_D$	0.80		
condition factor	CF	0.90		assume deteriorated
strength reduction factor	$\phi$	0.72		
dead load factor	$\gamma_D$	1.25		
overload factor	$\gamma_O$	1.49		
live load factor	$\gamma_L$	1.9		
eccentricity	e	1.0		
dead load effect	DL	4.0	kN	from dead load demands
rating load	0.85 HO	28.0	kN	from stringer LL demands
posting load	0.85 HN	17.0	kN	from stringer LL demands
with speed restriction? (yes/no)		yes		
speed limit (30/10)		10		
dynamic factor	$I_o$	1.30		
				with speed restriction for 30 km/h: $I = (I_o - 1) \times 0.67 + 1$ for 10 km/h: $I = (I_o - 1) \times 0.33 + 1$
corrected dynamic factor	I	1.10		
overload capacity	$R_O$	39	kN	$R_O = (\phi R_i - \gamma_D DL) / \gamma_O$
Rating load effect	RLE	31	kN	$RLE = 0.85HO \times I \times e$
Rating CLASS	<b>CLASS</b>	<b>127%</b>		$CLASS = R_O / RLE$
live load capacity	$R_L$	31	kN	$R_L = (\phi R_i - \gamma_D DL) / \gamma_L$
Posting load effect	PLE	19	kN	$PLE = 0.85HN \times I \times e$
Posting GROSS	<b>GROSS</b>	<b>164%</b>		$GROSS = R_L / PLE$

## **Appendix B** - (Bridge Inspection Reports)



CLIENTS | PEOPLE | PERFORMANCE

**Bridge Name:**  
Mangateitei Rail Overbridge

**Bridge No:**  
292

**Road:**  
Mangateitei

**RP:**  
844

Bridge Type: Timber deck on Hardwood (HW) beams on timber piers and concrete abutments				Report Type: Principal				
Piers: HW timber on concrete base		Pile Caps:		Unknown		Foundations: Concrete		
Deck Type: Timber		Deck width:		4.8 m		Deck Cantilever: 0 mm		
Running Planks: Full width running boards		Width (Kerb to kerb)		4.3 m		Deck Thickness: 100 timber + full width r/bs mm		
<b>Extent marking code</b> A = No Defect B = Not > 5% C = Moderate 5 - 20% D = Wide 20 - 50% E = > 50% N = Not Applicable NI= Not Inspected	<b>Severity code</b> 1 - as new 2 = early signs of defect 3 = moderate defect 4 = severe defect 5 = element failed	Total Bridge length:		17.4 m		Map Ref (easting): 2720881.595		
		Beams: 6 No. 350 x 240 avg. HW		Map Ref (northing): 6195236.034		Owner / Client: Ruapehu District Council		
		Spacing: 800 mm		Span: 3		Current Loading Sign: 70% Class 1		
		Span length: 5.3, 5.4, 5.3 m		Axle: 8,200 kg		Speed (km/h): 15 km/h		
		Height Above Water/Road: 4.806 m		Design Loading: Originally Class 1		Year Constructed: Unknown		
		Inspector: Etienne du Plessis		Date: 25-Mar-2021		Next Inspection Type: General		
		S = Structural Mtce ; R = Routine Mtce		Date: 25-Mar-2021		Date (mth/yr): 2023		
Element				Ext	Sev	S / R	Brief description of defect and comments	
Set	No	Description						
Superstructure Elements	1	Primary load carrying element		E	4	S	Timber Decay (main stringers old, cracks and decayed. Also peppered with core holes, SRF less than 0.80. Beam 3 & 4 severe weathering near abutment 1)	
	2	Secondary element(s)	Transverse beams	N				
	3		Other (incl. deck)	D	4	S	Broken Running boards (running boards badly worn)	
				C	4	S	Broken Cross beams North (timber decking requires urgent replacement near abutment 1)	
	4	Half joints		N				
	5	Seismic linkages/holding down bolts		N				
	6	Parapet beam or cantilever		D	3	S	Broken Kerbs	
Load-bearing Substructure	7	Cross bracing		N				
	8	Foundations		A				
	9	Abutments		B	2	R	Lichen / Moss / Vegetation Abutment (lichen covering concrete surface)	
	10	Head wall		A				
	11	Pier / column		B	3	S	Aged Pier (columns deteriorate / split "decayed" which in some cases have been bolted - SRF=0.80)	
	12	Cross-head / capping beam		C	3	S	Crack Pier Capping beam/bearing plinth (cross head longitudinal cracks/splitting)	
				E	3	S	Crack Pier (corbels show significant splitting/ cracking)	
Durability Elements	13	Bearings		N				
	14	Bearing plinth / shelf		C	2	R	Debris Abutment bearing plinth	
	15	Superstructure drainage		A				
	16	Substructure drainage		A				
	17	Movement / expansion joints		N				
	18	Painting: superstructure elements		N				
	19	Painting: substructure elements		N				
Safety Elements	20	Painting: barriers / guardrails		B	2	R	Paint Loss Handrails	
	21	Access / walkways / gantries		N				
	22	Guardrail / handrail / safety fences		C	3	S	Broken Handrails	
				E	3	S	Loose Handrails	
	23	Carriageway surfacing		N				
Waterway Elements	24	Footway/verge / footbridge surfacing		N				
	25	Invert / river bed		N				
	26	Aprons		N				
	27	River bed upstream		N				
	28	River bed downstream		N				
	29	Scour		N				
	30	River banks		N				
Retaining Element	31	Revetment / batter slope paving		N				
	32	Wing walls		A				
	33	Retaining walls		A				
	34	Embankments		A				
Other	35	Approach rails / barriers / walls		C	2	R	Missing Approach rails (both directions)	
	36	Approach adequacy		C	2	R	Settlement Approach South (also reason for surface deformation and heaving)	
	37	Signs		B	3	R	Missing Bridge end markers (BEM)	
	38	Lighting		N				
	39	Services		A				
	40	Appearance		D	4	S	Aged Deck (all timber members exceeded their life span and bridge to be replaced)	



CLIENTS | PEOPLE | PERFORMANCE

Bridge Name:  
Mangateitei Rail Overbridge

Bridge No:  
292

Road:  
Mangateitei

RP:  
844

**Comments and recommendations for maintenance/repairs**

Item no.	Element no.	Suggested remedial work	Priority (H/M/L)	Estimated cost
1.	1,11,40	Investigate (bridge assessment required and may be further restricted)	H	
2.	3	Replace (running board and first couple timber cross timber boards on approach North)	H	\$15,000 - \$20,000
3.	6	Replace (broken kerbs - 4 off)	M	\$7,500 - \$10,000
4.	11,12	Monitor (pier columns, capping beams and cobbles - no change from previous inspection)	H	
5.	22	Tighten Bolts (re-nail, brace cracked timbers and fix loose handrails)	M	\$5,000 - \$7,500
6.	20	Clean & Repaint (all timber rails)	L	\$5,000 - \$7,500
7.	23,36	Regrade, New Seal (Surface) (realign approach and repair deformed surface seal)	M	\$10,000 - \$15,000
8.	35	Install New (approach rails where missing)	H	\$2,500 - \$5,000
9.	37	Install New, Capacity Check (missing BEM and update restriction sign after assessment)	H	\$1,000 - \$2,500
10.	40	Monitor, Install New (provide surveillance system - overweight vehicles trespassing)	H	\$1,000 - \$2,500

**Total Cost**

Remedial work recommended in last inspection has been completed (*comment below if NO*):

**NO**

Bridge Database changes required (*Describe changes below if answer is yes*):

**NO**

**Comments & Recommendations Relating to Future Management (Transfer to current report)**

All the above items specified in the previous report were not completed - Bridge needed replacement

**Other Notes**

Surveillance system to be installed on the bridge as overweight vehicles been using the bridge.

Inspection by: Etienne du Plessis

Signature: 

Date: 29-Mar-2021

Reviewed by:

Signature:


Date:

Approved by:

Signature:

Date:

**Bridge Overview Photo**





## Element Photos

**1 : Primary load carrying element**

Timber Decay (main stringers old, cracks and decayed. Also peppered with core holes, SRF less than 0.80. Beam 3 & 4 severe weathering near abutment 1)







**3 : Secondary - Other (incl. deck)**

Broken Running boards (running boards badly worn)

Broken Cross beams North (timber decking requires urgent replacement near abutment 1)







**6 : Parapet beam or cantilever**

Broken Kerbs





**9 : Abutments**

Lichen / Moss / Vegetation Abutment (lichen covering concrete surface)

**11 : Pier / column**


Aged Pier (columns deteriorate / split "decayed" which in some cases have been bolted - SRF=0.80)







pier 2 - column 1 (transverse direction)



pier 2 - column 1 (longitudinal direction)



**12 : Cross-head / capping beam**

Crack Pier Capping beam/bearing plinth (cross head longitudinal cracks/ splitting)  
Crack Pier (corbels show significant splitting/ cracking)







**14 : Bearing plinth / shelf**

Debris Abutment bearing plinth







**20 : Painting : Barriers / guardrails**


Paint Loss Handrails



**22 : Guardrail / handrail / safety fences**

Broken Handrails

Loose Handrails







CLIENTS | PEOPLE | PERFORMANCE

Bridge Name:  
Mangateitei Rail Overbridge

Bridge No:  
292

Road:  
Mangateitei

RP:  
844



### 23 : Carriageway surfacing



### 35 : Approach rails / barriers / walls

Missing Approach rails (both directions)







CLIENTS | PEOPLE | PERFORMANCE

Bridge Name:  
Mangateitei Rail Overbridge

Bridge No:  
292


Road:  
Mangateitei

RP:  
844



### 36 : Approach adequacy

Settlement Approach South (settlement behind abutment - also reason for surface deformation and heaving)



### 37 : Signs

Missing Bridge end markers (BEM)







### 40 : Appearance

Aged Deck (all timber members exceeded their life span and bridge to be replaced)



### Supporting Photos



Approach South



Deck surface





CLIENTS | PEOPLE | PERFORMANCE

Bridge Name:  
Mangateitei Rail Overbridge

Bridge No:  
292

Road:  
Mangateitei

RP:  
844



Bridge Restriction Sign



Rail South East



Rail North West



Approach North East



Abutment 1



Pier 1





CLIENTS | PEOPLE | PERFORMANCE

Bridge Name:  
Mangateitei Rail Overbridge

Bridge No:  
292

Road:  
Mangateitei

RP:  
844



Pier 2



Abutment 2

GHD  
 Level 1 18 Manu aute Street  
 PO Box 334  
 Taumarunui  
 3946  
 New Zealand  
 T: +64 7 896 0121 E: [tmnmail@ghd.com](mailto:tmnmail@ghd.com)

© GHD 2021

This document is and shall remain the property of GHD. The document may only be used for the purpose for which it was commissioned and in accordance with the Terms of Engagement for the commission. Unauthorised use of this document in any form whatsoever is prohibited.

\\ghdnet\ghd\NZ\Taumarunui\Projects\51\34054\Technical\\_Bridges\Inspections\General\2020.2021 Inspections\Clarinsinspect\2020.2021 Bridge Inspections for Clarins Inspect\RB292 Mangateitei Rail Bridge 2021Document Status

Revision	Author	Reviewer		Approved for Issue		
		Name	Signature	Name	Signature	Date
0	Etienne du Plessis	Alex Chisholm		Stephen Fletcher		29/04/2021

[www.ghd.com](http://www.ghd.com)