EXISTING FACILITY ASSESSMENT

at THE ALFRED C. PRIESTLEY SCHOOL New Orleans, Louisiana

Waggonner & Ball *Architects* New Orleans, Louisiana

DESIGN TEAM

ARCHITECT

Waggonner & Ball Architects 2200 Prytania Street New Orleans, Louisiana 70130 t. 504-524-5308

David Waggonner Mac Ball Kenner Carmody Dennis Horchoff Charles Sterkx

CIVIL /STRUCTURAL ENGINEER

Schrenk, Endom and Flanagan 4141 Bienville Avenue #2 New Orleans, Louisiana 70119 t. 504-482-7856

Structural/Civil Consultant

Mr. Edmund Schrenk

MECHANICAL, ELECTRICAL, PLUMBING CONSULTANT

Moses Engineers 909 Poydras St # 2150 New Orleans, LA 70112 t. (504) 586-1725

MEP/Fire Protection Consultant

Mr. Lenny Zimmerman

OPINION OF PROBABLE COST

Pro-Serv Estimating
Mr. Tom Boudreaux

SURVEYOR

Gandolfo Kuhn, LLC Mr. Paul Kocke

Table of Contents

	Chapter 1: Executive Summary	
Section 1.1	Executive Summary	1
Section 1.2	Site Plan	6
Section 1.3	Existing Building Plans	8
Section 1.4	Existing Gym Plans	10
Section 1.5	Wall Sections	11
Section 1.6	Building Sections	13
Section 1.7	Exterior Elevations	17
	Chapter 2: Assessment	
Section 2.1	Civil / Site	19
Section 2.2	Structural	21
Section 2.3	Architectural	25
Section 2.4	Mechanical (HVAC, Plumbing & Fire Protection)	26
Section 2.5	Electrical (Power, Lighting & Special Systems)	30
	Chapter 3: Existing Conditions Photographs	
Section 3.1	Architectural Photographs	33
Section 3.2	Mechanical Photographs	66
Section 3.3	Fire Protection Photographs	69
Section 3.4	Electrical Photographs	70
	Chapter 4: Opinion of Probable Construction Cost	
Section 4.1	Architectural Summary & Recommendations	73
Section 4.2	Facility Redevelopment Plans, Options A, B & C	74
	Chapter 5: Appendices	
Section 5.1	Facility Report (Parsons)	81
Section 5.2	Reference Drawings (Parsons)	90
Section 5.3	Building Renovation Probable Construction Cost Estimate	98
Section 5.4	Gym Renovations Probable Construction Cost Estimate	104
Section 5.5	New Education Building Probable Construction Cost Estimate	110
Section 5.6	Archive Drawings	116

Waggonner & Ball Architects

CHAPTER 1 EXECUTIVE SUMMARY

Waggonner & Ball Architects, APC has been retained by Jacobs/CSRS Program Management to conduct an assessment of the Alfred C. Priestley School located at 1619 Leonidas Street on Square 208 which is bounded by Leonidas, Green, Joliet and Birch Streets in Uptown New Orleans.

An assessment of the structures on site with regard to structural systems, building envelope, civil, mechanical, electrical, fire protection and special systems is contained in this report. Waggonner & Ball was assisted by Schrenk, Endom and Flanagan Consulting Engineers (structural and civil) and Moses Engineers (mechanical, electrical, plumbing, fire protection and special systems.) A survey was conducted by Gandolfo Kuhn LLC to determine the amount of settlement in the three story classroom structure. Two separate site visits were conducted by the assessment team. This report does not provide for an assessment of hazardous materials. Specific designs have not been developed to resolve the deficiencies noted in the existing structures.

An opinion of probable cost has been developed to: A) Renovate the existing buildings for reuse as a stand-alone school facility (quantifying the number of classrooms); B) Renovate and expand both existing buildings to provide an 87,000 square foot 2-section per grade Pre-K through 8th grade school facility; and C) Demolish the existing gymnasium, renovate the three story classroom building and expand it to provide an 87,000 square foot 2-section per grade Pre-K through 8th grade school facility.

Building History and General Information

The Priestley School, which has not been in operation since well before Hurricane Katrina, once occupied the entire block, and had its main entrance on the Leonidas Street side. There are two separate structures on the site, a three story classroom building and a single story, highbay former recreation building or Gymnasium. Designed in 1937 as the Walter C. Flower Public School by architect E.A. Christy, the original three story bearing-wall masonry structure with wood windows was a building of approximately 26,380 square feet which included three one-story portions on the Joliet Street side that housed girls' and boys' toilet rooms, an electrical room and a boiler room. The entrance to the structure was from the north on the Leonidas Street side via a diagonal entry hall raised approximately 30 inches from grade and incorporated in a two-story wing on that side of the building. The entry has Art Deco brickwork detailing around the entrance doors. Copies of the original drawings (of poor quality) were located in the New Orleans Public Library and show that the exterior bearing walls and interior steel columns of the original building were supported by driven piles and concrete pile caps. In 1955 the school was expanded. As no drawings were found at the time of this report, the name of the architect is still unknown. A 7,300 square foot, three-story concrete frame classroom addition (with concrete pan joist floor system) of the same width as the original building was constructed at the Green Street end that incorporated a new concrete fire stair. Also constructed at that time was a separate masonry-walled gymnasium/recreation hall along with a one-story locker room addition along the rear of the original classroom building. The concrete and masonry detailing of the 1955 wing bears similarities to another E. A. Christy building, the Charles Colton School in the Marigny District, which building Waggonner & Ball is currently renovating for use as a Pre-K through 8th grade school. Exterior masonry wall expansion in that structure was not accounted for in the design. Expansion of the masonry caused the exterior wall to fail in that instance, necessitating a new masonry exterior for the entire building. The length of wall at Colton is far greater than that at Priestley, but similar problems are occurring at Priestley on a lesser scale (the masonry wall has expanded at the parapet corners.)

The single story gymnasium structure is approximately 6,735 square feet and is spanned with non-fireproofed semi-parabolic arched trusses spaced every 18 ft and roofed with what appear to be corrugated Transite roof panels. The Gym contains bleachers on both sides that are in poor condition. The underside of the exposed roof panels appears to be covered in mold or mildew.

Two separate trips were made to the site to assess and document the condition of the buildings. Both structures are in very poor condition from years of deferred maintenance and more recent vandalism. A full interior renovation, significant structural changes, and extensive work to the exterior envelope will be required to bring the structures up to current codes. A brief summary of the major deficiencies is listed below.

Building Code and Construction Type

As defined in the Uniform Building Code, the three story classroom building is a Type III structure (exterior walls of non-combustible materials with a fire-resistance rating of 2-hours; interior building elements of any building material permitted by Code.) For a fully-sprinklered Type III building of unprotected construction (unrated interior walls, floors and roof) used for Educational Occupancy, the maximum allowable number of stories is three (3) and the maximum floor area (per floor) is limited to 43,500 square feet. Per NFPA 13 (the Sprinkler Code), concealed spaces formed by the floor/roof joists do not have to be sprinklered provided that the ceilings are no more than 6 inches below the bottom of the framing.

The existing fire stairs do not meet current code (one is wood and one concrete) and there is no elevator serving the building. Reuse of the building for Educational occupancy will require significant masonry restoration, new code-compliant windows, a new roof, new demising partitions, ceilings, finishes, new fire alarm and sprinkler systems, and new MEP and special systems. The first floor slab has settled (it is not pile-supported) and a new slab will need to be constructed throughout. In order to use the building as a stand-alone school or an expanded one, it is probable that the one story additions on the Joliet Street side will need to be removed in order to provide daylighting for the first floor classrooms. The brick from these demolished portions should be carefully salvaged for reuse in the masonry restoration of the buildings.

The Gymnasium structure is a Type II building. Typically, buildings of different construction Types can be joined together, provided that the height and area limitations of the lesser Type are applied to the combined structure in its entirety.

Base Flood Elevation Determination

The Priestley buildings are in the original Carrollton Historic District, a National Historic District. That district is bounded by Lowerline Street, the Mississippi River, Monticello Avenue and Earhart Boulevard. An ordinance was passed by the New Orleans City Council in August 25, 2006 (approved August 30, 2006) amending Chapter 78 of the Code of the City of New Orleans to the effect that all properties in Nationally Registered Historic Districts are allowed to have their first floor elevation at base flood elevation (BFE) or 18" above the highest elevation of the street curb at the front of the property, whichever is greater. The classroom building meets this requirement. The Gymnasium, however, has settled such that it is slightly below the BFE and will need an additional 3" of concrete cast on top of the existing slab to get the floor level to 18" above the street curb.

The property is in an A-1 Flood Zone. It is our belief that future additions to the building(s) will be allowed to be at the same first floor elevation as the existing school. However, this will need to be verified and agreed to by the owner and FEMA, which negotiation is not within the scope of this report. The buildings are not currently on the National Register, but are considered historic due to the fact that they, including the 1955 gymnasium and 3 story classroom addition, are over fifty years old.

Deficiencies

Civil

- 1. Drainage: Subsurface storm drainage systems appear to be non-functional; requires video investigation/mapping, clearance of obstructions or replacement
- 2. Sidewalks: Many of the surrounding sidewalks are in poor condition and should be replaced as part of a full site development
- **3.** Parking lot: Existing parking lot paving surface is in poor condition and will need replacement or relocation, depending on the overall site development

Structural

Main Building

- 1. There are no expansion or control joints in the exterior masonry bearing walls, which is typical for buildings of this era. The entire building has settled differentially approximately 3½," with the high point at Green street and the low point at Birch Street. Cracked bricks need to be removed and replaced at approximately 40 locations (as shown on building elevations in this report)
- 2. There is no lateral bracing of the exterior masonry walls of the original structure
- **3**. First floor slab is not pile supported and must be replaced throughout with a new 5" thick slab with grade beams
- 4. Steel lintels at the window heads are water damaged and need replacement. Steel jamb and sill reinforcing will need to be incorporated to attach new code-compliant windows

Gymnasium

- 1. The top members of the trusses at each end of the building have rusted and will require further investigation and probable repair
- 2. The building has settled differentially $2\frac{1}{2}$ ", with the high point at the Green Street side and the low point at the Birch Street side

Architectural

Main Building

- Entire single-slope roof system and deck, parapet flashing and wall cap (and blocking) need to be replaced; new downspouts and leader heads required
- 2. Building is uninsulated
- 3. New code-compliant/wind rated windows and exterior doors required throughout
- 4. Masonry restoration, repair and repointing of entire exterior required
- 5. New fire stairs required (2 total)
- **6.** Entire interior needs to be demolished leaving only structural wood framing at floor levels and corridor walls
- 7. Entire interior requires a full build-out, dependent upon program of spaces required; detailing at corridors and exterior windows should emulate the original design with raised panel doors with glass paned upper panels and transoms, wood base, wood chair-rails and wood door and window trim consistant with the original fabric.
- 8. New elevator required
- 9. New site fencing required for entire perimeter of city block
- 10. New landscaping and play equipment required

Gymnasium

- 1. New code-compliant/wind rated windows and exterior doors required throughout
- 2. New roof required (standing seam metal over new plywood deck)
- 3. Roof insulation required
- 4. Concrete floor needs to be topped to bring floor elevation to BFE
- **5.** Roof trusses not fireproofed; requires further code investigation as it relates to full buildout
- 6. Paint interior walls and provide athletic floor finish
- 7. Replace deteriorated bleachers

Mechanical (HVAC, Plumbing and Fire Protection)

1. New mechanical, plumbing, and automatic sprinkler/fire protection systems required throughout both structures

Electrical (Power, Lighting and Special Systems

1. New electrical service, electrical systems, building and site lighting, fire alarm, telephone, data, security, lightning protection and other special systems required throughout both structures

Aerial Site Photograph











Existing Site Plan




















Existing Main Building Wall Section Scale: 1/8" = 1'-0"

1955 Building Addition Wall Section Scale: 1/8" = 1'-0"

CHAPTER 2 SITE & BUILDING ASSESSMENT

Section 2.1 Civil / Site Assessment

Based on visual observation and historical experience, it is our opinion that the subsurface drainage system will need to be replaced. The sewer system will need to be replaced, as well as all water systems. The interior sidewalks also need to be replaced. The perimeter sidewalks, which are in poor condition presently, will be further damaged during construction and will need to be replaced. The parking area has deteriorated as well and will probably need replacement as part of a larger renovation / expansion project.

The ground surface has subsided approximately 6" so some additional fill will be needed when the buildings are renovated and expanded. The property has a number of large live oaks and water oaks at its perimeter. There are seven (7) large oaks on both Leonidas and Green Streets and one oak on Joliet and Birch Streets, both in poor condition.

Section 2.2 Structural Assessment

The purpose of this section is to offer a preliminary opinion on the structural condition of the facility. This opinion is based on a walk-through of the property conducting visual observations, and a review of the 1938 construction documents. Also reviewed were elevation readings at the perimeter brick course of the classroom building and elevations taken on the floor of the gymnasium. These recorded elevations were the work of Gandolfo Kuhn, LLC, Civil Engineers and Land Surveyors and the survey was performed on April 13, 2012.

Building Description

The 1938 building is three stories and was designed and built using exterior masonry walls and wood floor framing with interior bearing stud walls on each side of a central corridor. The floor and ceiling joists are 2 x 14's and are spaced at 16"o.c. One of the corridor walls was eliminated in the center of the building to open a larger cafeteria space on the ground floor. The load from the eliminated bearing wall is supported on a network of structural steel beams and columns. The masonry exterior bearing walls and the interior wood bearing walls are supported on concrete grade beams which in turn are pile supported. The length and capacity of the piling were not indicated. The boiler room at the rear of the building is not framed in wood. It is a one story structure with a concrete poured-in-place pan joist system as the roof structure.

In approximately 1955 a three story addition was added to the Green Street side of the main school building with a detached one-story gymnasium. There were no available construction documents for these additions. The three story addition is a concrete poured-in-place pan joist floor system with concrete beams and columns.

The gymnasium was constructed with a barrel shaped roof supported on structural steel trusses with "X" bracing in the opposite direction. The walls of the gymnasium consist of brick and CMU. The building, but not the floor slab, is assumed to be supported on timber piles, but this could not be verified.

Observations

Classroom Building:

Observations were made of existing conditions that were accessible. Building finishes were not removed in connection with these observations. Calculations of existing framing were not part of the scope. The timber framing observed was in generally good condition, with the exception of localized water-damaged members. This damage, in most cases, could be traced to water leaks in the roof. Every third floor and roof joist was tied positively to the masonry walls. This was done with a flat steel bar anchored to the joists and hooked into the masonry wall. The ends of the joists at the masonry pockets were treated with tar. The interior wood stud walls were not accessible to view because of wall coverings.

The exterior masonry walls are three wythes thick. There are no expansion or control joints in the masonry walls, which was typical for this era of construction. However, masonry cracking was observed in approximately forty locations. At the front parapet along Leonidas Street, approximately 240 SF of masonry had been replaced at some time in the past, but has again cracked. It also appears that the masonry parapet has been replaced (or repointed) on the Birch Street side.

Elevations were taken on the protruding brick course of the main building above the first floor. The results indicate that the building has settled differentially $3\frac{1}{2}$ "; the high point is on the Green Street side and the low point is on the Birch Street side. There is no positive lateral load element in the building except the exterior walls. The first floor slab is not pile supported and is in very poor condition.

Gymnasium:

It was noted that the top members of the two end trusses have rusted. The other framing members appear to be in good condition. Elevations were taken by Gandolfo Kuhn, LLC, on the finished floor. The readings indicated that the slab has settled differentially $2\frac{1}{2}$ ", and like the classroom building, the high side is along Green Street and the low side along Birch Street. Masonry wall cracking was noted in four locations.

Recommendations and Estimated Cost

1. Place two steel K-braces in the classroom building to supplement the lateral load resistance in the building.

Estimated cost: \$250,000

2. Replace 88 steel lintels in the classroom building over all exterior doors and windows.

• Estimated cost: \$160,000

3. Remove and replace cracked bricks on each side of the 40 cracks in the main building and four cracks in the gymnasium. Place $\frac{1}{4}$ " stainless steel rod x 2'-6" at every third brick course across the repaired crack. We are recommending to repair the masonry cracks, but recognize that masonry cracking will continue because of the lack of masonry control joints and the differential settlement.

Estimated cost: \$290,000

4. Replace the first floor slab in the classroom building with a 5" reinforced concrete slab

• Estimated cost: \$207,000

5. Repair wood framing that has been damaged and that was noted in our walk-through.

• Estimated cost: \$25,000

6. We would recommend that a thermal imaging program be implemented to document water and termite damage to the wood framing members. This would better define any damage to the wood. Additional damage uncovered by the thermal imaging would be an additional repair cost.

 Possible Contact: Gurtler Bros. Consultants 622 City Park Avenue New Orleans, LA 70119 504-486-8500

Section 2.3 Architectural Assessment

With the 1955 addition, the main building is approximately 33,680 square feet with 13,767 sf at the ground floor, 10,194 sf at the second floor and 9,719 sf at the third floor. The building has a small attic or crawl space and a low pitched roof which drains to the Joliet side of the building.

The floors and wall partitions of the classroom building are wood-framed, with 2 \times 14 floor joists that are pocketed into the masonry bearing walls. The upper two floors are laid out with classrooms on either side of a central, nine foot wide corridor with stairs at either end. The first floor has some larger areas that were used for recreation rooms and a cafeteria. This necessitated the incorporation of a wide flange steel beam at the second floor level to support the corridor wall above. This beam is supported by wide flange steel columns that rest on pile caps. The majority of the first floor level is at grade with the entrance and former kitchen being the only raised portion of the first floor.

The main building is in poor shape, due to differential settlement and to the removal of four copper gravity ventilators at the roof that have allowed water to enter the building for a number of years, causing damage to the third floor deck and joists. In addition, probably at the same time, the copper coping protecting the masonry parapet walls was removed leaving exposed wood blocking at that condition. There is also evidence of termite infestation throughout the building. According to an earlier report conducted after Hurricane Katrina the site reportedly sustained an estimated foot of flood water from the storm. It is unclear whether flood water entered the buildings.

The exterior masonry walls are showing signs of settlement and cracking at multiple locations, typically at the parapets, parapet corners and at the window sills. It appears that a large portion of the parapet on both the Leonidas and Birch Street elevations were either rebuilt or repointed at some point. The southeast parapet corner of the 1955 addition has also shifted approximately two inches due to a lack of expansion joints in the exterior walls. The parapet in the original structure is approximately three feet high on the Joliet Street side. It is approximately six feet high in the 1955 addition due to the lack of an attic or crawl space in that portion of the building.

See Section 3.3, page 67, for Mechanical Reference Images

	CONF	CONFORMS			ION	COMMENTS		
	YES	NO	NA	GOOD	MAINTENANCE REQUIRED	REPAIR	REPLACE	
Window Units		Х					Х	No longer in- place (Image M01)
Heating Boilers		Х					Х	No longer in- place (Image M02)
Radiators		Х					Х	Non-functional, not re-usable (Image M03)
Piping		Х					Х	Non-functional, not re-usable (Image M04)
Fan systems		Х					Х	Non-functional, not re-usable (Image M05)
Components		Х					Х	Non-functional, not re-usable

Section 2.4 Mechanical Assessment

The heating system in-place appears mostly original to the building and consists of hot water convectors or radiators, with hot water unit heaters augmenting the radiators where required. This methodology for heat is effective, but obsolete. Coupled with the facts that the steel piping system has been inactive and abandoned to rust for so many years and that the boilers have been removed, this system should be removed and replaced in its entirety with heating that integrates into a modern HVAC system.

The only mechanical ventilation provided for the main building was exhaust fans to remove heat and odors and wall mounted propeller fans to provide ventilation in the Gymnasium. The only source of outdoor air was infiltration through doors and operable windows. This methodology is no longer allowed by modern Codes and a ventilation system integrated into a modern HVAC system will be required to place the building in-service.

Air conditioning for the main school building was not provided as part of the original construction and was an afterthought consisting of window air conditioners which have been removed and were wired by way of exposed conduits and outlets and controlled by manual wall switches. The Gymnasium was not air conditioned.

Mechanical Summary & Recommendations

To place the facility in-service, a modern HVAC system must be installed to provide heating, cooling and ventilation to the both buildings.

Plumbing Assessment

Plumbing systems appear original to the building and consist of vitreous china lavatories and toilets in restrooms. All kitchen fixtures have been removed. While the hot, cold and drainage piping systems serving the existing fixtures remain in-place, it's most likely that the many years of non-use have allowed them to deteriorate to the point of being unusable.

Plumbing Summary & Recommendations

- 1. The fixtures themselves appear, for the most part, to be in decent condition; however, they do not meet current standards for water usage efficiency and should be replaced as the building is placed back inservice.
- 2. Exposed storm drainage piping is no longer continuous and must be replaced.

See Section 3.3, page 68, for Reference Images

PLUMBING									
	CONFORMS			CONDIT	TON	COMMENTS			
	YES	NO	NA	GOOD	MAINTENANCE REQUIRED	REPAIR	REPLACE		
Domestic Water		Х					Х	Non-functional, not re-usable	
Sanitary System		Х					Х	Non-functional, not re-usable	
Gas Service		Х					Х	Non-functional, not re-usable	
Storm Water		Х					Х	Non-functional, not re-usable (Image P01)	
All components		Х					Х	Non-functional, not re-usable (Image P02)	

Fire Protection Assessment

Fire protection sprinklers were provided to a portion of the building only. While the sprinkler control valve assembly is intact, as is much of the piping and sprinkler heads, it's unlikely these components are in working order due to the length of inactivity and would not be reusable in a system of full sprinklers required by current Codes.

Fire Protection Summary & Recommendations

A complete automatic fire sprinkler system must be provided for the entire facility.

See Section 3.5, page 69, for Reference Images

	CONFORMS			CONDIT	ION	COMMENTS		
	YES	NO	NA	GOOD	MAINTENANCE REQUIRED	REPAIR	REPLACE	
Sprinkler System		X					X	Only installed on ground floor, non-functioning, not reusable (Image FP01)
All components		X					Х	Non-functioning not-re-usable

See Section 3.4, page 70, for Reference Images

	CONFORMS			CONDIT	COMMENTS			
	YES	NO	NA	GOOD	MAINTENANCE REQUIRED	REPAIR	REPLACE	
Power Distribution		X					Х	Gutted, not re- usable (Image E01)
Power Components		X					Х	Non-functional not re-usable (Image E02)
Lighting		X					Х	Non-functional not re-usable (Image E03)
Lighting Components		X					Х	Non-functional not re-usable (Image E04)

	CONFORMS			CONDIT	COMMENTS			
	YES	NO	NA	GOOD	MAINTENANCE REQUIRED	REPAIR	REPLACE	
Fire Alarm		X					Χ	Does not exist
Telecommunications		X					X	Does not exist
Public Address		X					Х	Non-functional not re-usable
Access Control		X					X	Does not exist
CCTV		X					X	Does not exist

Section 2.5 Electrical Assessment (Power, Lighting & Special Systems)

Existing electrical power systems for the building are of several vintages indicating renovations over the life of the building, not the least of which was the addition of window air conditioners. Many of the augmented systems were accomplished with surface mounted panelboards and unsightly exposed conduit and wiring systems


All of the electrical service equipment and much of the distribution equipment and copper wiring has been cannibalized and the electrical systems in their entirety must be replaced, in order to place the facility back in-service. Electrical devices such as switches and receptacles are, for the most part, intact; however, they are obsolete and must also be replaced

Electrical lighting systems and their branch circuits also still, for the most part, exist; however, not only would the cost to refurbish the existing systems be prohibitive, but also, the existing fixtures are obsolete and do not provide the quality and quantity of light, as well as energy efficiency required by present Codes

Electrical Summary & Recommendations

Special systems components such as fire alarm, telephone wiring, intercom, and public address exist at some level, while others such as data wiring and security systems do not exist. In order for the facility to be functional to today's standards, all electrical and special systems must be replaced

CHAPTER 3 EXISTING CONDITIONS PHOTOGRAPHS



Site Plan Photograph Key





A1 Main Entry



A3 Northwest Façade



A2 Main Entry




A4 Joint at Addition on Northwest Side




A5 Joint at Addition on Northwest Side-Ledge



A6 Northwest Façade



A7 Main Entry Facing Southwest



A8 Northwest Façade at Addition




A11 Rebuilt Brick Parapet at Northwest Side



A9 Northwest Façade



A13 Trees Along Leonidas Street



A10 Northwest Façade



A14 Handrail at Main Entry



A12 Masonry Crack at Northwest Façade



A15 Southwest Façade



A16 Southwest Façade



A18 Asphalt Paved Yard Facing East (Green and Joliet)



A20 Patterned Brick and Building Sign above Main Entry



A17 Play Yard Facing West Corner (Birch and Leonidas)



A19 Flagpole at Main Entry



A21 Exterior Window at South Stair



A23 Exterior Joint at Addition



A22 Exterior Southwest Corner



A24 Exterior- Crack Below Sill



A25 Exterior- Typical Wood Window



A26 Paving at Main Entry



A27 Exterior- Southeast Corner




A28 Plant Growth in Masonry at Boiler Room



A31 Wood Windows and Copper Downspouts-Leaderheads



A29 Exterior- Southeast Façade



A30 Masonry Crack Below Sill at Façade



A32 Northwest Façade of Gym



A33 Gym Roof



A34 South Corner of Gym



A36 Masonry Crack Adjacent to Window



A35 Southest Façade at Addition



A37 Area Between Gym and Main Building Facing Northeast



A38 Watertable Course in Masonry at Main Building



A40 Play Yard Facing South Corner (Birch and Joliet)



A42 Masonry Cracks in Gym Wall



A39 Gym South Corner



A41 Gym from Roof of Main Building



A43 Southeast Façade at Addition



A44 North Corner of Gym



A46 Parapet East Corner



A45 North Corner of Addition



A47 Masonry Movement at Parapet



A48 Exterior- Northwest Side



A50 Southeast Façade




A49 Paving at Northeast Side



A51 Masonry Cracking Adjacent to Boiler Stack



A52 Joint at Addition Looking Down from Roof




A53 Area Between Gym and Main Building Facing Southwest



A54 Northeast Corner Facing Gym



A55 Northeast Corner



Second Floor Plan North

Existing Conditions of Interior Photographs



A101 North Stair at Addition



A103 Existing Kitchen



A105 Typical Window Condition



A102 Cafeteria Facing Gym



A104 Cafeteria Facing Southwest



A106 Settlement at First Floor Slab



A107 Termite Damage at Door Frame



A109 Sprayed Finish at Concrete Addition



A111 Typical First Floor Exterior Doors



A108 Exposed Brick at Addition



A110 Walls, Base and Chair Rail



A112 Existing Stair at Main Entry



A113 Raised Platform at Main Entry



A114 Dish Wash Room



A115 Typical First Floor Interior Door



A116 Non-original Partitions



A117 Typical Chalkboard with Wood Trim



A118 Termite Damage at Interior Woodwork



A120 Transfer Beam Under Loadbearing Corridor Wall at Floors Above



A122 Boiler Room



A119 Typical Exposed Sprinkler and Electrical at Cafeteria



A121 Exterior- Window at South Stair



A123 Boiler Room



A125 Second Floor Corridor Facing South



A124 Second Floor Corridor Facing North



A126 South Stair at Second Floor



A127 Termite Damage at Window Stool



A128 Second Floor Toilet Room




A130 South Stair to Main Entry




A129 Clock System Control Panel



A131 Typical Built-In Classroom Storage





Floor Plans and Photograph Key

North



A132 Built-in Storage at Coat Room



A133 Typical Wood Floor Framing



A134 Typical Corridor Door to Classroom



A135 Wall Calendar from Last Occupants



A136 Typical Light Fixture



A138 Third Floor Classroom



A137 South Stair at Third Floor



A139 Third Floor Corridor Facing South



A140 Third Floor Corridor Facing North



A141 Typical Classroom Door-Transom at Second and Third Floors



A142 Damage at South Stair Guardrail




A143 Toilet Room Second Floor



A201 Roof Looking South



A203 Parapet at Addition Looking Northeast



A202 Parapet at Addition Looking Northeast



A204 Existing Gravel-Ballasted Low Slope Roof

Existing Conditions of Roof Photographs



A205 Masonry at Boiler Stack



A207 Main Entry Roof from Above



A209 Roof at Main Building




A206 Main Entry and Soutwest Wing from Roof




A208 Parapet Condition at Joint Between Addition and Original Building




A301 Gym Interior Facing Northwest



A303 Gym Interior Facing Northeast



A304 Gym Interior Facing North



A302 Gym Interior Facing Southeast



A305 Steel Framing at Gym


Existing Conditions of Gym Photographs



A306 Gym Interior Facing Southeast



A307 CMU and Brick Vertical Coursing at Gym



	CONF	CONFORMS			ION	COMMENTS		
	YES	NO	NA	GOOD	MAINTENANCE REQUIRED	REPAIR	REPLACE	
Window Units		Х					Х	No longer in- place (Image M01)
Heating Boilers		Х					Х	No longer in- place (Image M02)
Radiators		Х					Х	Non-functional, not re-usable (Image M03)
Piping		Х					Х	Non-functional, not re-usable (Image M04)
Fan systems		Х					Х	Non-functional, not re-usable (Image M05)
Components		X					Х	Non-functional, not re-usable



M01 Missing Window Unit



M03 Non-Functioning Radiator



M05 Non-Functioning Fan



M02 Missing Boilers



M04 Non-Functioning Piping



P01 Non-Functioning Storm Water



P02 Non-Functioning Sink

PLUMBING								
	CONFORMS			CONDIT	ION	COMMENTS		
	YES	NO	NA	GOOD	MAINTENANCE REQUIRED	REPAIR	REPLACE	
Domestic Water		Х					Х	Non-functional, not re-usable
Sanitary System		Х					Х	Non-functional, not re-usable
Gas Service		Х					Х	Non-functional, not re-usable
Storm Water		X					Х	Non-functional, not re-usable (Image P01)
All components		Х					Х	Non-functional, not re-usable (Image P02)



FP01 Non-Functioning Sprinkler Rig

	CONFORMS			CONDI	ION	COMMENTS		
	YES	NO	NA	GOOD	MAINTENANCE REQUIRED	REPAIR	REPLACE	
Sprinkler System		X					X	Only installed on ground floor, non-functioning, not reusable (Image FP01)
All components		X					Х	Non-functioning, not-re-usable



E01 Gutted Power Distribution



E02 Non-Functional Components



E03 Non-Functioning Lighting



E04 Non-Functioning Components

	CONF	CONFORMS			CONDITION				
	YES	NO	NA	GOOD	MAINTENANCE REQUIRED	REPAIR	REPLACE		
Power Distribution		X					Х	Gutted, not re- usable (Image E01)	
Power Components		X					Х	Non-functional not re-usable (Image E02)	
Lighting		Х					Х	Non-functional not re-usable (Image E03)	
Lighting Components		X					Х	Non-functional not re-usable (Image E04)	

	CONFORMS			CONDIT	COMMENTS			
	YES	NO	NA	GOOD	MAINTENANCE REQUIRED	REPAIR	REPLACE	
Fire Alarm		X					X	Does not exist
Telecommunications		X					X	Does not exist
Public Address		X					Х	Non-functional not re-usable
Access Control		X					X	Does not exist
CCTV		X					X	Does not exist

CHAPTER 4 OPINION OF PROBABLE COST OF CONSTRUCTION

Architectural Summary & Recommendations

Three options were requested with regard to the use of the buildings and site. The first option was to determine the number of classrooms that the three story building could accommodate and to provide a plan and order of magnitude cost for the renovation of the buildings as a standalone facility, knowing that the structures do not contain enough square footage for any of the school facility models the owner is considering.

The second option was to renovate the existing buildings (renovate the existing gymnasium building as a gymnasium) and show a plan and massing for new construction to bring the site up to a 2 section per grade Pre-Kindergarten through Eighth Grade school of 87,000 sf. The existing gymnasium building is marginally acceptable as a middle school basketball court with regard to size and clearances in plan—however, it does not meet the height requirements for a middle school gymnasium facility at the edges of the basketball court. An alternate strategy might be to make the existing gymnasium structure into the cafeteria and kitchen and construct a new regulation size gymnasium.

The third option was to renovate the three story classroom building, demolish the gym and expand the existing building to a 2 section per grade Pre-Kindergarten through Eighth Grade school of 87,000 sf. This option would include a new gymnasium in place of the demolished former gymnasium.

OPTION A: RENOVATION OF EXISTING BUILDINGS FOR CLASSROOM USE (no new construction)

The buildings are in such a deteriorated condition that this project would require a complete restoration of the exterior and extensive demolition and renovation of the interior, leaving only the structural framing intact. We are unsure of the amount of the structural framing (stud walls and wood floor joists and roof framing) that are sound, but our opinion from visual observation is that the majority of the wood appears to be in good shape. This will require further investigation and possibly thermal imaging testing. The existing building could accommodate approximately 18 classrooms as shown in the plan diagrams below.

Other than the stainless steel (or aluminum) school name sign, it appears that there are no items of historical value to salvage or restore. The list of work items below was developed to establish a cost model for renovating the existing buildings (the only addition being an exterior fire stair tower at the Green Street end.)

Work required for a full renovation would include, but not be limited to:

Classroom Building

Exterior Work:

- 1. New roof deck, insulation and modified bitumen roof, parapet flashings and parapet cap
- 2. Repointing of all the exterior masonry including lacing in brickwork at all existing masonry cracks at window heads and sills and at parapets; replace all steel window lintels; clean masonry; install steel angles at window jambs.
- **3**. Demolish one story portions of the building on the south(Joliet Street) side and repair masonry
- 4. Install new painted steel, code-compliant/wind rated windows and doors with high impact glazing; install new steel lintels at all window and door openings and steel jamb and sill angle supports at all windows.
- **5.** Install new masonry fire stair structure at Green Street end of the building

Interior Work:

- **6.** Install new 5" thick ground floor slab and grade beams throughout structure; termite-treat ground surface
- 7. Strip corridor walls down to wood studs; new steel stud framing for demising partitions; new drywall throughout
- **8.** Install new 3 5/8" studs and batt insulation at exterior walls; new drywall
- **9**. Install insulation between floor joists throughout and install 2 layers of drywall at bottom of joists
- **10**. Install new layer of ¾" plywood over existing flooring in classroom areas with VCT as floor finish; salvage wood flooring for reuse in corridors
- **11**. Install millwork elements (window and door trim, cabinets, cubbies, etc.)
- 12. Install new interior steel stairs
- **13**.Install 2 new interior steel K- braces for lateral support (see Structural section)
- 14. Install new wood doors and transoms and wood trim throughout interior; install hollow metal doors and frames at exterior
- **15**. Install new 2' x 2' acoustical ceiling grid and panels throughout
- **16.** Install terrazzo floor finish in first floor corridors and entry hall

- 17. Install new finishes throughout entire building (w/ceramic tile walls and floors and drywall ceilings in all toilet rooms)
- **18.** Install one (1) new handicapped-accessible elevator
- **19**. Install all new mechanical, electrical, plumbing, fire protection and special systems throughout
- **20.** Install window coverings, lockers, marker boards and other equipment and accessories

Gymnasium Building:

Exterior Work:

1. Repair masonry cracks by lacing salvaged bricks across joints per structural recommendations

Interior Work:

- 1. Install mechanical, electrical, plumbing, fire protection (sprinkler and fire alarm), special systems
- 2. Install 3" topping slab
- 3. Install bleachers and athletic equipment
- 4. Install synthetic (sheet) gym flooring surface
- 5. Prepare and paint interior surfaces of exterior walls
- **6.** Install new hollow metal doors and frames; install new code-compliant/wind rated windows
- 7. Repair rusted steel roof trusses and paint; insulate underside of roof

Sitework:

The scope of sitework is undefined and unquantifiable at present as this assessment was for the condition of the buildings. However, a square foot cost estimate has been provided for the existing amount of open space in order to establish an order of magnitude budget for site development.

COST OF REPAIR AND RENOVATION WORK FOR OPTION A: (pricing breakdown provided in Appendix):


Three Story Classroom Building: \$7,068,141.00 Gymnasium Structure: \$1,254,722.00


 TOTAL COST OPTION A:
 \$8,322,863.00


 contingency
 +10%

 \$832,286.30

\$9,115,149.30







OPTION B: RENOVATE BOTH EXISTING BUILDINGS FOR REUSE AND CONSTRUCT ADDITIONS FOR TWO-SECTION PER GRADE PK-8TH GRADE SCHOOL

The scope of work for the renovation of the existing buildings would be the same as for Option A. The new building additions in Option B would involve a one story connector to the existing Gymnasium and a three story classroom, administration and cafeteria addition and entry hall along the Birch Street side of the site. New additions would be steel-framed structures (with 2 hr fireproofed perimeter columns and beams) with brick veneer (CMU backup on the ground floor) and a combination of brick veneer and metal panel with steel stud backup on the upper floors. Roof areas would be modified bitumen. A parking lot would logically be located at the corner of Green and Joliet Streets and could accommodate approximately 16 vehicles. In addition there are 50 on-street parallel parking spots on the perimeter of the site. Play areas would be on the river side along Birch Street. A small, separate Pre-Kindergarten play area could also be located along Green Street. Service for the kitchen could be accessed from Joliet Street or from the parking area. A site plan for Option B is included on the facing page.

Three Story Classroom Building: \$7,068,141.00 Gymnasium Structure: \$1,254,722.00 Existing Construction to be renovated: \$8,322,863.00

New Construction: 49,265 sf x \$229/sf = \$11,297,497.00

 TOTAL ESTIMATED COST OPTION B:
 \$19,620,360.00

 contingency
 +10%
 \$1,962.036.00

 ***1,962.036.00
 ***1,962.036.00

\$21,582,396.00

TOTAL EXISTING: 37, 735 SF PROPOSED NEW: 49, 265 SF

PROJECT TOTAL: 87,000 SF





OPTION C: RENOVATE EXISTING CLASSROOM BUILDING ONLY AND CONSTRUCT ADDITIONS FOR TWO-SECTION PER GRADE PK-8th Grade School

The scope of work for the existing 3 story classroom building would be the same as for Option A. This option would include the demolition of the existing circa 1955 gymnasium structure. The new additions in Option C (same construction as in Option B) would include a new entry, a gymnasium, additional classrooms, administration offices, a kitchen and cafeteria. The U-shaped building would form a play court and allow for additional play space along the Birch street side of the site. A small Pre-Kindergarten play area could be located along Green Street in the same location as that in Option B. On-site parking in Option C would be limited. However, there are approximately 50 on-street parallel parking spaces on the school side of the perimeter of the block. A Site plan for Option C is included on the facing page.

Existing Three Story Classroom Building to be Renovated: \$7,068,141.00New Construction: 56,000 sf x \$229/sf = \$12,824,000.00

TOTAL ESTIMATED COST OPTION C:

\$19,892,141.00

<u>contingency</u> +10% \$1,989,214.10

\$21,881,355.10


SUMMARY

In summary, the existing buildings are notable, historic and worth preserving if feasible with regard to cost and the goals of the Owner. Pre World War II structures such as the original building contribute to the historic district and character of the neighborhood and should be retained if at all possible. Further, it was designed by City architect E.A. Christy whose dozens of schools and fire houses are woven into the historic fabric of New Orleans.

The problems that have been identified with regard to settlement of the structures and the cracking brickwork are typical of many of the masonry bearing wall structures throughout the City. Most of the valuable real estate in the Vieux Carre is constructed of masonry bearing walls that exhibit similar problems. The masonry cracks will reappear over time as the building continues to slowly settle, but the measures put forth in this report should limit this problem to a great extent, and these buildings should be able to serve a long term purpose as a modern school facility.

TOTAL EXISTING: 31, 000 SF PROPOSED NEW: 56, 000 SF

PROJECT TOTAL: 87, 000 SF



Site Plan- Option C North

CHAPTER 5 APPENDICES

Section 5.1	Facility Report (Parsons)	81
Section 5.2	Reference Drawings (Parsons)	90
Section 5.3	Estimate Recap/Detail Existing Building Renovation	98
Section 5.4	Estimate Recap/Detail Gym Building Renovation	104
Section 5.5	Estimate Recap/Detail New Building Addition	110
Section 5.6	Archival Drawings	115

Report Date: 13 Aug 2008

Orleans Parish Schools

COMET4 Facility Report Facility Executive Summary Report

Facility: \OPSB Schools\Priestley 999

Address: 1619 Leonidas St., New Orleans, LA 70118

Attributes: ***None***

General Information:

Function: Middle / Junior High

Facility Description:

GENERAL

The vacant Priestley Jr. High School #999 is located at 1619 Leonidas Street in New Orleans, LA. The Main Building on campus is a 3-story, 32,834 square foot building that was originally constructed in 1955. There is also a Gymnasium which was built sometime after the Main Bldg, perhaps in 1955; it has 6,548 square feet of floor space. There have been numerous renovations, but we have no documented information. The school campus has been abandoned and unoccupied since 1993 and not maintained with the exception of the site landscaping and grass mowing which has been maintained at a minimum level. During the assessment survey it was observed certain storm-attributable deficiencies had occured, and no reports of renovations had been performed. Based on GIS query of the site against National Oceanic and Atmospheric Administration (NOAA) public flood maps, this facility campus reportedly sustained an estimated one (1) foot of storm floodwater in the aftermath of Hurricane Katrina. The only apparent evidence of storm damage at this site was wind damage to roof, but this is not conclusive due to the abandoned state of the facility. The facility has extensive damage and most is beyond repair. There is evidence of termite infestation.

SITE

Surface parking is available on site. There is an asphalt area which can be used for parking but none out of approximately 15-20 potential spaces are handicap spaces and path to building entrances appears to not comply with ADA requirements. Parking striping does not exist. Landscaping is mature, is in fair condition and is not irrigated. Drainage is generally inadequate and is handled by surface discharge and limited area drains. Concrete sidewalks immediately adjacent to the facility are in poor condition. There appears to be inadequate site lighting for vehicular and pedestrian night traffic. The water supply is provided from the campus distribution system and appears to be in poor condition. Fire water is provided from a campus fire water distribution system. The campus sanitary sewer system appears to be in poor condition. Storm water removal is provided by the campus storm water system and surface runoff to the adjacent streets. The heating distribution system includes hot water supply and hot water return piping to and from the boiler room. The piping is in poor condition; however, the boilers have been removed. The cooling distribution system included window air conditioning units that were removed several years ago. Priestly Jr. High was abandoned prior to Hurricane Katrina.

SUBSTRUCTURE

The building typically rests on concrete footings and foundation walls that are showing signs of settlement and damage. The building does not have a basement.

SHELL

The superstructure is concrete and wood beams with double wide brick walls. Floor construction is a combination of wood and metal pan with concrete fill. Roof construction is wood. The exterior enclosure is comprised of walls of double wide brick walls. Exterior windows are wood frame with operable lites. Exterior doors are solid core wood. Roofing is typically low-slope with built-up roofing and is in poor condition with unreported leaks. Entrances do not comply with ADA requirements.

INTERIORS

Interior construction partition wall types typically include painted concrete block, plaster, etc. Interior doors are generally solid core/hollow wood doors and frames. Interior fittings include chalk and tack boards, shelving and toilet partitions in poor condition. Toilet configurations and accessories are inadequate and appear to not comply with ADA requirements. Interior graphics and/or signage are inadequate and appear to not comply with ADA requirements. Stair construction includes wood risers and treads with wood finishes. The interior wall finishes are typically plaster and generally in poor condition. Floor finishes in common areas are typically vinyl composition tile. Floor finishes in assignable spaces are typically vinyl tile. Ceiling finishes in common areas are typically plaster that is in poor condition. Ceiling finishes in assignable areas are typically plaster that is in poor condition.

SERVICES

Conveying: The building does not include conveying equipment.

Plumbing: Fixtures are in poor condition. Domestic water distribution is galvanized steel with some copper and is in poor condition, with reports of the water main line being broken. The sanitary waste system is cast iron and is in poor condition. The rain water system is external with roof scuppers, gutters and downspouts in poor condition.

HVAC: Heating was provided by gas-fired boilers which were removed from the premises at an unknown date. Cooling was supplied by an unknown number of window units. The heating distribution system was a 2-pipe system connected to radiators and unit heaters. Fresh air was supplied by natural infiltration. Ceiling and/or wall-mounted exhaust fans are installed in most bathrooms, but ventilation is inadequate. Controls and instrumentation are primarily manual, with a few analog/mercury bulb thermostats, and are not centrally controlled by an energy management system.

Fire Protection: The building has a fire sprinkler system. Standpipes are not included within fire stairs. Fire extinguishers and cabinets are not distributed near fire exits and corridors.

Report Date: 13 Aug 2008

Orleans Parish Schools

COMET4 Facility Report Facility Executive Summary Report

Electrical: The electrical service is fed from pole-mounted transformers that deliver 120-240 volts, 1-phase, 3-wire power and 120/208 volts, 3-phase, 4-wire power to main panels. Power distribution wiring from branch panels is typically copper, 3-wire grounded and is inadequate. Lighting and branch wiring is typically 3-wire grounded serving recessed, surface-mounted and pendent-mounted fluorescent lighting fixtures. Illumination is generally inadequate throughout the school. Emergency power is not available. Emergency lighting apparently was not present in the school building. Exit signs were present at some exit doors and were typically illuminated.

Communications and Security: The fire alarm system consisted of audible annunciators in common spaces and appeared to not comply with ADA requirements. The system is activated by pull stations and is not centrally monitored. The system needs to be upgraded to comply with current code requirements. The telephone and data systems are separate and do not include dedicated closets or cabinets that are adequately secured and cooled. The building does not have a public address (PA) system. The building does not include an internal security system that is actuated by contact, infrared, optical or any combination of such devices and is not centrally monitored.

Other Electrical Systems: The building does not have an emergency generator. The building does not have a dedicated grounding system and does not have a lightning protection system.

EQUIPMENT & FURNISHINGS

The building does not include fixed food service, darkroom, library, theater and stage, audio-visual, detention, laboratory, medical or mortuary equipment. The building does include fixed casework furnishings that are in poor condition.

SPECIAL CONSTRUCTION

The building does not include special construction.

COSTING

The material list is based on typical constructions and RS Means cost estimating methods for the representative building type. Cost Estimates are directly derived from RS Means Commercial Composite Cost Data.

Current Repair Cost: \$7,070,586.00



31-Jan-2008



31-Jan-2008

Replacement Cost: \$8,805,202.00



31-Jan-2008




31-Jan-2008

Deferred Maint Index: 80.30%



31-Jan-2008

Deficiency Estimate By Assembly OPSB Schools/999 Priestley



Report Date: 13 Aug 2008

Orleans Parish Schools

COMET4 Facility Report

Facility Executive Summary Report

Facility: \OPSB Schools\Priestley 999 \Building 1-Main

Attributes: Building Type Main Building (Office / Admin

/ Classroom)

Type School **OSPB**

General Information:

Function: Middle / Junior High Year Built: 1938 32,834 S.F. **Gross Area: Last Renovation:**

Facility Description:

Current Repair Cost: \$5,449,052.00





Replacement Cost: \$6,731,894.00

30-Jan-2008



30-Jan-2008

Deferred Maint Index: 80.94%



30-Jan-2008



30-Jan-2008

Report Date: 10 Jul 2008

Orleans Parish Schools

COMET4 Facility Report Facility Executive Summary Report

Facility: \OPSB Schools\Priestley 999 \Building 1-Main (continued)

Renewal Schedule:

Systems	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018
Total	\$5,449,053					\$262,097					\$981,917
Substructure											
Foundations											
Standard Foundations											
Shell	\$708,858										
Superstructure											
Floor Construction											
Roof Construction											
Exterior Enclosure	\$597,943										
Exterior Walls											
Exterior Windows	\$551,019										
Exterior Doors	\$46,924										
Roofing	\$110,915										
Roof Coverings	\$110,915										
Built-Up	\$110,915										
Interiors	\$1,623,332					\$262,097					\$458,629
Interior Construction	\$567,297				-	Ψ202,037					\$154,787
Partitions	\$364,977				1						ψ104,101
Interior Doors	\$87,144										
	\$115,176										\$154,787
Fittings	\$115,176										\$154,787
Stairs											
Stair Construction											
Interior Finishes	\$1,056,035					\$262,097					\$303,842
Wall Finishes	\$226,087					\$262,097					\$303,842
Paint & Covering 70%	\$226,087					\$262,097					\$303,842
Floor Finishes	\$392,148										
VCT 60%	\$392,148										
Ceiling Finishes	\$437,800										
Plaster Ceilings	\$246,298										
Acoustical Ceilings	\$191,502										
Services	\$2,916,980										\$523,288
Plumbing	\$285,778										\$33,537
Plumbing Fixtures	\$193,179										
Domestic Water Distribution	\$24,955										\$33,537
Rain Water Drainage	\$20,720										
Sanitary Waste	\$46,924										
HVAC	\$1,732,339										\$225,220
Energy Supply	\$495,441										
Ventilation & Exhaust	\$24,803										
Heat Generating Systems	\$601,477										
Boilers, Hot Water & Steam	\$601,477										
Distribution Systems	\$443,033										
Controls & Instrumentation	\$167,585										\$225,220
Fire Protection	\$22,548										
Sprinklers	\$22,548										
Electrical	\$876,315			-							\$264,531
Electrical Service/Distribution	\$78,003			-	-						Q204,001
Lighting and Branch Wiring	\$579,538			-	-	-					
Communications and Security	\$196,836			-		-					\$264,531
	\$196,836										φ204,331
Other Electrical Systems											
Equipment & Furnishings	\$199,883										
Furnishings	\$199,883										
Fixed Furnishings	\$199,883										

Report Date: 13 Aug 2008

Orleans Parish Schools

COMET4 Facility Report Facility Executive Summary Report

Facility: \OPSB Schools\Priestley 999 \Building 2-Gymnasium

Attributes: Building Type Gym OSPB Type School

General Information: Function: Middle / Junior High Year Built: 1955

Gross Area: Last Renovation: 6,548 S.F.

Facility Description:

Current Repair Cost: \$943,019.00



Replacement Cost: \$1,419,116.00







Deferred Maint Index: 66.45%

31-Jan-2008



31-Jan-2008

Report Date: 10 Jul 2008

Orleans Parish Schools

COMET4 Facility Report Facility Executive Summary Report

Facility: \OPSB Schools\Priestley 999 \Building 2-Gymnasium (continued)

Renewal Schedule:

Systems	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018
Total	\$943,019					\$28,037		\$59,518			\$188,708
Substructure											
Foundations											
Foundations											+
Shell	\$92,789										+
Superstructure											+
Roof Construction											+
Exterior Enclosure	\$44,517										+
Exterior Walls											+
Exterior Windows	\$44,517										
Exterior Doors											
Roofing	\$48,272										
Roof Coverings	\$48,272										
Interiors	\$254,389					\$28,037		\$59,518			\$131,674
Interior Construction	\$48,114					\$28,037					\$64,661
Partitions											
Interior Doors	\$23,929										\$32,159
Fittings	\$24,185					\$28,037					\$32,502
Interior Finishes	\$206,275							\$59,518			\$67,013
Wall Finishes	\$48,394							\$59,518			1
Floor Finishes	\$108,017										1
Ceiling Finishes	\$49,864										\$67,013
Services	\$558,288										\$57,034
Plumbing	\$76,041										\$10,976
Plumbing Fixtures	\$52,015										
Domestic Water Distribution	\$8,167										\$10,976
Rain Water Drainage	\$5,833										
Sanitary Waste	\$10,026										
HVAC	\$310,281										\$10,943
Terminal & Package Units	\$156,289										
Ventilation & Exhaust	\$145,849										
Controls & Instrumentation	\$8,143										\$10,943
Electrical	\$171,966										\$35,115
Electrical Service/Distribution	\$19,323										
Lighting and Branch Wiring	\$125,177										
Communications and Security	\$26,129										\$35,115
Other Electrical Systems	\$1,337										
Equipment & Furnishings	\$37,553										
Furnishings	\$37,553										+
Fixed Furnishings	\$37,553			-							+

Report Date: 13 Aug 2008

Orleans Parish Schools

COMET4 Facility Report Facility Executive Summary Report

Facility: \OPSB Schools\Priestley 999 \Site

Attributes: ***None***

General Information:

Function: Middle / Junior High **Year Built:** 1938

Gross Area: 90,378 S.F. **Last Renovation:**

Facility Description:

SITE

Surface parking is available on site. There is an asphalt area which can be used for parking but none out of approximately 15-20 potential spaces are handicap spaces and path to building entrances appears to not comply with ADA requirements. Parking striping does not exist. Landscaping is mature, is in fair condition and is not irrigated. Drainage is generally inadequate and is handled by surface discharge and limited area drains. Concrete sidewalks immediately adjacent to the facility are in poor condition. There appears to be inadequate site lighting for vehicular and pedestrian night traffic. The water supply is provided from the campus distribution system and appears to be in poor condition. Fire water is provided from a campus fire water distribution system. The campus sanitary sewer system appears to be in poor condition. Storm water removal is provided by the campus storm water system and surface runoff to the adjacent streets. The heating distribution system includes hot water supply and hot water return piping to and from the boiler room. The piping is in poor condition; however, the boilers have been removed. The cooling distribution system included window air conditioning units that were removed several years ago. Priestly Jr. High was abandoned prior to Hurricane Katrina.

Current Repair Cost: \$678,515.00



19-Feb-2008



19-Feb-2008

Replacement Cost: \$654,192.00



19-Feb-2008



19-Feb-2008

Deferred Maint Index: 103.72%



19-Feb-2008

Orleans Parish Schools

COMET4 Facility Report Facility Executive Summary Report

Report Date: 10 Jul 2008

Facility: \OPSB Schools\Priestley 999 \Site (continued)

Renewal Schedule:

Systems	2008	2009	2010	2011	2012	2013	2014	2015	2016	2017	2018
Total	\$678,514										\$84,311
Services	\$180,825										\$84,311
Electrical	\$180,825										\$84,311
Electrical Service/Distribution	\$118,090										
Communications and Security	\$62,735										\$84,311
Building Sitework	\$497,689										
Site Preparation											
Site Earthwork											
Site Improvements	\$185,690										
Parking Lots	\$86,722										
Pedestrian Paving	\$18,452										
Site Development	\$27,677										
Landscaping	\$52,839										
Site Mechanical Utilities	\$199,277										
Water Supply	\$25,832										
Sanitary Sewer	\$123,626										
Storm Sewer	\$49,819										
Site Electrical Utilities	\$112,722										
Site Lighting	\$112,722										

Space Inventory Report

999

Priestly Junior High


Permanent Buildings


Build	ling Number and Name	Year	Floors	Area (SF)	
01	01_Main Building	1945	3	32,834	
02	02_Gymnasium	1955	ţ	6,548	
2	Total Buildings	Tot	al Area:	39,383	

Permanent Area Analysis


Space Type		Area (SF)	# Rooms
Classrooms		12,058	19
Media Center		1,124	1
Physical Education		8,994	8
Student Dining		4,090	8
Administration		3,578	21
Assigned Storage		224	4
Public Restrooms		1,260	6
Building Support		1,273	13
Horizontal Circulation		4,822	11
Laboratory		992	3
Open Space		68	ı
	Total Area	38,483	95


Note: The area difference between the Permanent Buildings total and the Permanent Area Analysis total is associated with walls and structure not measured in the area analysis.






File Name: 999_Priestley M







Estimate Recap

444 Red Maple Dr Mandeville LA, LA 70002 Phone: 504888-9433 Fax: 504886-6997

Estimate File: Priestley School Existing Building.est - Priestley School existing Building, New Orleans

Estimator: Primary Project Qty:31000 SF Estimate UM:Imperial

Sort Sequences: 1. Divisions 2. Not Used 3. Not Used 4. Not Used 4. Not Used

				Repo	rt include	s Taxes &	Insurance. I	ndirect cost	Report includes Taxes & Insurance. Indirect costs are Spread.
7:41:38AM									5/3/2012
Description	Labor \$	Material \$	Equipt \$	qns \$	Temp Matl \$	Equipt Rntl \$	Other Costs \$		Item Total \$
General requirements				\$434,671					\$434,671
Site work & demolition				\$380,059					\$380,059
Concrete				\$155,478					\$155,478
Masoniy				\$276,406					\$276,406
Metals				\$103,652					\$103,652
Wood and plastics				\$587,363					\$587,363
Thermal and moisture protection				\$526,621					\$526,621
Doors and windows				\$656,465					\$656,465
Finishes				\$1,036,523					\$1,036,523
Specialties				\$190,029			_		\$190,029
Equipment				\$103,652					\$103,652
Furnishings				\$103,652					\$103,652
Special construction				\$69,102					\$69,102
Conveying systems				\$112,290			-		\$112,290
Mechanical				\$1,572,060					\$1,572,060
Electrical Company of the State				\$760,117					\$760,117
ESTIMATE TOTALS				\$7,068,141					\$7,068,141

All Items S:\Program files\MC2 Software\datafiles\mc2pj.std

Deignation Cohool evicting Duild	5								
Priesuey School existing building Pro-Serv estimating LLC	5 =								
444 Red Maple Dr Mandeville LA								31,000 SF	,
		Labor	Material	Equipment	Subcontract	Temp Mati Equip Renta		Other	Totals
Direct costs	%						Ma.		
Base labor		\$0		\$0	\$6,341,750	\$0	 &	\$0	\$6,341,750
Labor burden	20.00%	\$0		15 10 10 10 10 10 10 10 10 10 10 10 10 10		- 2400 - 1000 - 1000			\$0
Labor fringes	Į	\$0							\$0
Labor manhours_		0				ia ()			
Material sales tax	9.00%		- \$0						\$0
Equipment Surcharge	0.00%		-	\$0					0\$
						31., 1.			
Temporary material markup	0.00%					0\$	1.4 1.7 1.2 2.3 2.3 2.3 3.3		\$ 0
Equipment rental markup	0.00%						\$0	_	\$ 0
Other markup	0.00%							\$0	\$0
Gross cost		\$0	\$0	°, 08	\$6,341,750	- \$0	°\$0	\$0	\$6,341,750
General Liability Ins.	0.90%		**						\$63,613
Builder's risk insurance	0.65%								\$45,943
and the second s	Overall	The state of the s	and the second s			7	The second secon		
Overhead	0	%00:0	0	%00 ^{.0}			%00.0	%00.0	
	i,	80	\$0	\$0	\$0	7	\$0	80	\$0
Profit	8.00%	0	0.00%	0.00%			0.00%	%00.0	
	\$507,340	\$0	\$0	\$0	\$0	\$0	\$0	\$0	\$507,340
Subcontract bond	%00.0								\$0
Performance bond	\$55,777								\$55,777
Owner's Protective	0.10%								\$7,068
New Orleans B.P.	%99.0								\$46,650
Total									\$7,068,141
Cut/Add									0\$
	1、 1、 1、 1、 1、 1、 1、 1、 1、 1、 1、 1、 1、 1						物質的 体育 はない		((()

Pro-Serv estimating LLC 444 Red Maple Dr Mandeville LA, LA 70002 Phone: 504888-9433 Fax: 504888-6997

Estimate Detail

Estimate File: Priestley School Existing Building.est - Priestley School existing Building, New Orleans

Estimator: Primary Project Qty: 31000 SF Estimate UM:Imperial

Sort Sequences: 1. Divisions 2. Not Used 3. Not Used 4. Not Used

Report DOES NOT include Taxes & Insurance or Indirect Costs.

7:41:16AM				J				5/3/2012
		LINO	UNIT COSTS		TOTAL COSTS			
ltem Code Description	Quantity	Labor Material	Sub Equipt \$ \$	Labor I	Material Sub	Equipt \$	Total Unit \$	Item Total \$
01 General requirements		,						
1310.110 General Conditions	6.00 MO	0.00	40,000.00	\$0.00	240,000.00	00	40,000.00	240,000
1900.100 Project contingency	1.00 LS	0.00	150,000.00	\$0.00	150,000,00	00	150,000.00	150,000
Total General requirements					\$390,000	8	ı	\$390,000
02 Site work & demolition								
2000.000 Demolition (Selective)	31,000.00 SQFT	0.00	8.00	\$0.00	248,000.00	00	8.00	248,000
2200.000 Site Package	31,000.00 SQFT	0.00	3.00	\$0.00	93,000.00	.00	3.00	93,000
Total Site work & demolition					\$341,000	8		\$341,000
03 Concrete								
3000.000 Concrete	31,000.00 SQFT	0.00	4.50	\$0.00	139,500.00	0	4.50	139,500
Total Concrete					\$139,500	8	•	\$139,500
04 Masonry								
4200.000 Masonry restorations	31,000.00 SQFT	00.0	B.00	\$0.00	248,000.00	8	8.00	248,000
Total Masonry					\$248,000	8	1	\$248,000
05 Metals								
5000.000 Structural (Misc)	31,000,00 SQFT	0.00	3.00	\$0.00	93,000.00		3.00	93,000
Fotal Metals					000'86\$	8	1	\$93,000
06 Wood and plastics								
6200.000 Rough Carpentry (wood frame)	31,000.00 SQFT	0.00	10.00	\$0.00	310,000.00		10.00	310,000
6400.000 Finish carpentry	31,000.00 SQFT	00.0	7.00	\$0.00	217,000.00	00	7.00	217,000
Total Wood and plastics					\$527,000	8	1	\$527,000
07 Thermal and moisture protection								
7120.000 Waterproofing	31,000.00 SQFT	0.00	7.00	\$0.00	217,000.00	00	7.00	217,000
7210.000 Insulating package	31,000.00 SQFT	0.00	3.00	\$0.00	93,000,00	00	3.00	93,000
7520.000 Roofing (modified bit)	12,500.00 SQFT	0.00	13.00	\$0.00	162,500.00	8	13.00	162,500

2. Not Used 3. Not Used 4. Not Used

Sort Sequences: 1. Divisions

Primary Project Qty: 31000 SF Estimate UM:Imperial Report DOES NOT include Taxes & Insurance or Indirect Costs. Estimate File: Priestley School Existing Building.est - Priestley School existing Building

Item Total \$ \$472,500 93,000 124,000 465,000 93,000 124,000 310,000 \$170,500 108,500 \$589,000 155,000 170,500 93,000 \$93,000 62,000 100,750 248,000 \$930,000 \$62,000 5/3/2012 \$100,750 15.00 10.00 9.4 3.00 5.50 3.00 3.00 3.25 3.50 4.00 2.00 Total Unit \$ Equipt S 124,000.00 165,000.00 124,000.00 310,000.00 55,000.00 \$93,000 \$62,000 248,000.00 248,000.00 93,000.00 70,500.00 62,000.00 \$589,000 93,000.00 \$93,000 93,000.00 108,500.00 930,000 100,750.00 \$100,750 \$170,500 TOTAL COSTS Material \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 \$0.00 Labor Equipt 10.00 15.00 4.00 8 00 3.00 4.00 5.00 5.50 3.00 3.00 2.00 3.25 3.50 Sub UNIT COSTS Material 0.00 0.0 0.0 000 0.00 0.00 0.00 80 0.00 0.00 000 0.00 0.00 Labor 31,000.00 SQFT 31,000,00 SQFT 31,000.00 SQFT Quantity otal Thermal and moisture protection Description 8000.000 Doors Frames Hardware 11000.000 Equipment Package 13000.000 Special construction 10000.000 Specialties package 12000.000 Furnishing package 15400.000 Plumbing Package 9600.000 Flooring package Total Special construction 14200.000 Elevator Package Total Doors and windows 13 Special construction Total Conveying systems 08 Doors and windows 9250,000 Drywall Package 8800.000 Glass & Glazing 14 Conveying systems 9900.000 Paint package 15300.000 Fire Protection 9300.000 Tile package 9510.000 Acoustics Total Furnishings **Fotal Specialties** Total Equipment 12 Furnishings 10 Specialties 11 Equipment **Total Finishes** 15 Mechanical 09 Finishes 7:41:16AM tem Code

Sort Sequences: 1. Divisions
2. Not Used
3. Not Used
4. Not Used

Estimator. Primary Project City: 31000 SF Estimate UM:Imperial

				Repo	Report DOES NOT include Taxes & Insurance or Indirect Costs.	Taxes & Insu	rance or Indirect	Costs.
7:41:16AM	Estimate File: P	Priesdey School Existing Building.est - Priestley School existing Building	ng Building.est - Pries	stley School existin	g Building			5/3/2012
		ONILC	JNIT COSTS		TOTAL COSTS			
rem Code Description	Quantity	Labor Material \$	Sub Equipt	Labor Mate	faterial Sub	Equipt S	Total Unit \$	tem Total\$
15700.000 Mechanical Package	31,000,00 SQFT	0.00	34 00	\$0.00	1,054,000.00		34.00	1,054,000
Total Mechanical					\$1,410,500			\$1,410,500
16 Electrical								
16000.000 Electrical	31,000.00 SQFT	0 00	22.00	\$0.00	682,000.00		22.00	682,000
Total Electrical					\$682,000			\$682,000
ESTIMATE TOTALS					\$6,341,750			\$6.341.750

Estimate Recap

Pro-Serv estimating LLC 444 Red Maple Dr Mandeville LA, LA 70002 Phone: 504888-9433 Fax: 504888-6997

Sort Sequences: 1. Divisions 2. Not Used 3. Not Used 3. Not Used 4. Not Used

Estimate File: Priestley School Existing Gym.est - Priestley School existing Building, New Orleans

Primary Project Cty:6750 SF Estimate UM:Imperial Estimator:

\$117,147 \$29,287 \$51,252 \$43,930 \$21,965 \$21,965 \$36,608 \$18,304 \$36,608 \$43,930 \$14,643 \$245,277 \$222,363 \$234,294 \$117,147 \$1,254,722 5/4/2012 Report includes Taxes & Insurance, Indirect costs are Spread. Item Total \$ Other Costs \$ Equipt Rntl \$ Temp Matl\$ \$21,965 \$43,930 \$21,965 \$234,294 \$117,147 \$51,252 \$36,608 \$36,608 \$14,643 \$245,277 \$117,147 \$18,304 \$43,930 \$222,363 \$1,254,722 Sub \$ Equipt \$ Material \$ Labor \$ Description Thermal and moisture protection **ESTIMATE TOTALS** General requirements Special construction Doors and windows Wood and plastics Furnishings Mechanical Specialties Equipment 10:57:36AM Electrical Concrete Sitework Finishes Masonry Metals

Estimate Summary								Bid date	5/4/2012
Priestiey School existing Building Pro-Serv estimating LLC	<u>G</u>								
444 Red Maple Dr Mandeville LA								6,750 SF	L
\		Labor	Material E	Fourthment	Subcontract	Temn Mati	Temn Mati ≅anin Beata	Offbar	Totale
Direct costs	%					man direct	Direction of the beautiful of the beauti	2	
Base labor		© \$	_ &	\$0	\$1,156,750	©\$	- 80 	0\$	\$1,156,750
Labor burden 50	50.00%	\$0						•	0\$
Labor fringes		\$0							0\$
Labor manhours		0		<u> </u>		-			
Materia sales tax	%00.6		\$0						0\$
Equipment Surcharge of	0.00%			\$0					80
Temporary material markup	0.00%	-				\$0		•	80
2.3	%00.0						80		0\$
Other markup	0.00%						-	\$0	0\$
Gross cost		. \$0	- 80	- \$0	\$1,156,750	0\$	0\$	0\$	\$1,156,750
General Liability Ins.	%06.0								\$11,292
Builder's risk insurance	0.65%								\$8,156
0	Overall				:				
Overhead 0.00%	. 0.00%	%00.0	0.00%	0.00%	%00 ⁰ 0	0.00%	0.00%	%00.0	
	\$0	\$0	0 \$		\$0			\$0	0\$
Profit (%)	5.00%	0,00%	0.00%	o	%00'0		0.00%	0.00%	
	57,838	\$0	\$0	\$0	\$0				\$57,838
	0.00%								0\$
	\$11,151								\$11,151
Owner's Protective	0.10%					ē.	,	-	\$1,255
New Orleans B.P.	0.66%								\$8,281
Control of the Total									\$1,254,722
Cut/Add									\$0
Project total									\$1,254,722

Estimate Detail

Pro-Serv estimating LLC 444 Red Maple Dr Mandeville LA, LA 70002 Phone: 504888-9433 Fax: 504888-6997

Estimate File: Priestley School Existing Gym.est - Priestley School existing Building, New Orleans

Estimator: Primary Project Qty: 6750 SF Estimate UM:Imperial

Sort Sequences: 1 Divisions 2. Not Used 3. Not Used 4. Not Used 4. Not Used

Report DOES NOT include Taxes & Insurance or Indirect Costs.

10:57:07AM						. "	5/4/2012
		LINO	UNIT COSTS		TOTAL COSTS		
ttem Code Description	Quantity	Labor Material	Sub Equipt	Labor Mat \$	Material Sub Equipt \$	rt Total Unit \$	Item Total \$
01 General requirements			 				
1310.110 General Conditions	4.00 MO	0.00	40,000.00	\$0.00	160,000.00	40,000.00	160,000
1900.100 Project contingency	1.00 LS	0.00	45,000.00	\$0.00	45,000.00	45,000.00	45,000
Total General requirements				-	\$205,000		\$205,000
02 Sitework							
2000.000 Demolition (Selective)	6,750.00 SQFT	0.00	3.00	\$0.00	20,250.00	3.00	20,250
2200.000 Site Package	6,750.00 SQFT	0.00	1.00	\$0.00	6,750.00	1.00	6,750
Total Sitework					\$27,000		\$27,000
03 Concrete					-		
3000.000 Concrete	6,750.00 SQFT	00.0	7.00	\$0.00	47,250.00	7.00	47,250
Total Concrete			·		\$47,250		\$47,250
04 Masonry							
4200.000 Masonry restorations	6,750.00 SQFT	00.00	6.00	\$0.00	40,500.00	6.00	40,500
Total Masonry					\$40,500		\$40,500
05 Metals							
5000.000 Structural (Misc)	6,750.00 SQFT	0.00	3.00	\$0.00	20,250.00	3.00	20,250
Total Metals					\$20,250		\$20,250
06 Wood and plastics			·				
6200.000 Rough Carpentry (wood blkg)	6,750.00 SQFT	0.00	1.00	\$0.00	6,750.00	1.00	6,750
6400.000 Finish carpentry	6,750.00 SQFT	0.00	2.00	\$0.00	13,500.00	2.00	13,500
Total Wood and plastics					\$20,250		\$20,250
07 Thermal and moisture protection							
7120.000 Waterproofing	6,750.00 SQFT	0.00	3.00	\$0.00	20,250.00	3.00	20,250
7520.000 Roofing (standing seam)	6,750.00 SQFT	0.00	13.00	\$0.00	87,750.00	13.00	87,750

Sort Sequences: 1. Divisions
2. Not Used
3. Not Used
4. Not Used

Estimator. Primary Project City. 6750 SF Estimate UM:Imperial

			nestiey School Existing Gym.est - Priestiey School existing Building	est - Presut	y School exist	ing Bullain	5			5/4/2012
			8			TOTAL COSTS	OSTS			
	Quantity	Labor Mate \$	Material Sub \$ \$	Equipt \$	Labor 8	Material \$	Sub \$	Equipt \$	Total Unit \$	Item Total \$
Total Thermal and moisture protection							\$108,000		1	\$108,000
08 Doors and windows										
8000.000 Doors Frames Hardware 6,75	6,750.00 SQFT	0.00	2.00		\$0.00		13,500.00		2.00	13,500
8800.000 Glass & Glazing 6,75	6,750 00 SQFT	0.00	3 00		\$0.00		20,250.00		3.00	20,250
Total Doors and windows							\$33,750			\$33,750
09 Finishes									•	
9250.000 Drywall Package 6,75	6,750.00 SQFT	0.00	2.00		\$0.00		13,500.00		2.00	13,500
9600.000 Flooring package 6,75	6,750.00 SQFT	0.00	25.00		\$0.00		168,750.00		25.00	168,750
9900.000 Paint package 6,75	6,750.00 SQFT	00.0	5.00		\$0.00		33,750.00		2.00	33,750
Total Finishes							\$216,000		<u> </u>	\$216,000
10 Specialties										
10000.000 Specialties package 6,75	6,750.00 SQFT	00.0	2.50		\$0.00		16,875.00		2.50	16,875
Total Specialties						1,	\$16,875			\$16,875
11 Equipment										
11000.000 Equipment Package 6,75	6,750.00 SQFT	00.00	5.00	<u>-</u>	\$0.00		33,750.00		2.00	33,750
Total Equipment						<u> </u>	\$33,750			\$33,750
12 Furnishings										
ig package	6,750.00 SQFT	00.00	9.00		\$0.00		40,500.00		9	40,500
Total Furnishings							\$40,500		1	\$40,500
13 Special construction										
13000.000 Special construction 6,75	6,750.00 SQFT	0.00	2.00		\$0.00		13,500.00		2.00	13,500
Total Special construction							\$13,500			\$13,500
15 Mechanical	-			,						
15300.000 Fire Protection 6,75	6,750.00 SQFT	0.00	3.50		\$0.00		23,625.00		3.50	23,625
15400.000 Plumbing Package 6,75	6,750.00 SQFT	00.00	5.00		\$0.00		33,750.00		5.00	33,750
15700.000 Mechanical Package 6,75	6,750.00 SQFT	0.00	25.00		\$0.00		168,750.00		25.00	168,750
Total Mechanical	•			<u>'</u>			\$226,125		1	\$226,125
16 Electrical										
ical	6,750.00 SQFT	0.00	16.00		\$0.00		108,000.00		16.00	108,000
				•			-			

Sort Sequences: 1. Divisions 2. Not Used 3. Not Used 4. Not Used

Estimator: Primary Project Qty: 6750 SF Estimate UM: Imperial

					Report DOE	S NOT include	Taxes & Insur	Report DOES NOT include Taxes & Insurance or Indirect Costs.	t Costs.
77AM	Estimate File:	ile: Priestley School Existing Gym.est - Priestley School existing Building	ing Gym.est - Priesti	ey School ex	cisting Buildi	jug Jug			5/4/2012
Description	Ouandiv	UNIT COSTS Labor Material Sub	OSTS Sub Equipt	Labor	TOTAL COSTS	Sub Sub	Equipt	Total	fem
MATE TOTALS					•	\$1,156,750			\$1,156,750

Pro-Serv estimating LLC 444 Red Maple Dr Mandeville LA, LA 70002 Phone: 504888-6997

Estimate Recap

Estimate File: Priestley School New Educational Bldg.est - Priestley School existing Building, New Orleans

Report includes Taxes & Insurance. Indirect costs are Spread. Sort Sequences: 1. Divisions 2. Not Used 3. Not Used 4. Not Used Estimator. Primary Project Qty.49400 SF Estimate UM:Imperial 7:39:59AM

7:39:59AM							5/3/2012
Description	Labor \$	Material \$	Equipt \$	Sub Temp \$ Mati \$	p Equipt \$ Rntl \$	Other Costs \$	Item Total \$
General requirements				\$389,916			 \$389,916
Sitework				\$347,783			 \$347,783
Concrete				\$909,587			 \$909,587
Masonry				\$749,072			\$749,072
Metals				\$1,284,123		-	\$1,284,123
Wood and plastics				\$267,526			 \$267,526
Thermal and moisture protection	~			\$439,305			\$439,305
Doors and Windows				\$856,082			\$856,082
Finishes				\$1,658,659			\$1,658,659
Specialties			-	\$107,010			\$107,010
Equipment				\$642,061			 \$642,061
Furnishings				\$160,515			 \$160,515
Special construction				\$107,010			\$107,010
Conveying systems				\$141,789		~~	\$141,789
Mechanical				\$2,166,957			\$2,166,957
Electrical				\$1,070,102			 \$1,070,102
ESTIMATE TOTALS		 		\$11,297,497		- 1	\$11,297,497

All Items S:\Program files\MC2 Software\datafiles\mc2pj.std

A9,400 SF A9,4	Priestley School existing Building Pro-Serv estimating LLC	ng								
Base labor So So So So So So So	444 Red Maple Dr Mandeville LA							•	19,400 SF	
Base labor 10			Labor		quipment	1343	Temp Matigui	ip Renta	Other	Totals
Labor burden \$0 \$0 Labor manhours \$0 \$0 Labor manhours \$0 \$0 Material sales tax \$00% \$0 Requipment Surcharge \$00% \$0 Corray material markup \$00% \$0 Corray material markup \$00% \$0 Contract markup \$00% \$0 Chimarkup \$0 \$0 Chimarkup \$0 \$0 Chimarkup \$0 \$0 Subcommerce \$0 <td></td> <td>%</td> <td>U</td> <td>S</td> <td></td> <td>110 430 710</td> <td>Ç</td> <td>Ş</td> <td>G</td> <td>\$10.430.710</td>		%	U	S		110 430 710	Ç	Ş	G	\$10.430.710
Labor fringes	Labor burden	50.00%) Q		1 2000	134) • • • • • • • • • • • • • • • • • • •	}) }	05
Labor manhours	Labor fringes		\$0			ett.	15 15 15 15 15 15 15 15 15 15 15 15 15 1			0\$
Equipment Surcharge	Labor manhours		0							
Equipment Surcharge		9.00%		- \$0						\$0
Subcontract bond Subcontract	Equipment Surcharge	%00.0			\$0					\$0
Subcontract bond Subcontract										
Commerce Commerce	Temporary material markup	%00.0					\$0	\$40 100 200 500		\$0
Other markup \$0.00% \$0 \$0 \$0 \$0 \$10 \$0 \$10 \$0 \$10 \$0 \$10 \$0 \$10 \$0 \$10 \$0 \$10 \$0 \$10 \$0 \$10 \$0 \$10	Equipment rental markup	0.00%						\$0		\$0
General Liability Ins. 0.90% \$0 \$10.430,710 \$0 \$10.430,710 \$0 \$10.430,710 \$0 \$10.430,710 \$0 \$10.430,710 \$0 \$10.430,710 \$0 \$0 \$0 \$0 \$0 \$0 \$0	Other markup	%00.0							\$0	\$0
0.90% 0.65% Overall 5.00% 0.00% 0.00% \$0.00% \$84,280 0.10% 0.66%	Gross cost		0 \$	0\$		\$10,430,710	. 20	0\$	0\$	\$10,430,710
0.65% Overall 0.00% \$0 \$0.00% \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	General Liability Ins.	%06.0								\$101,677
Overall Overall \$0.00% \$.00% \$.00% \$.00% \$.00% \$0 \$0 \$0 \$0 \$0 \$5.00% \$.00% \$.00% \$0 \$0 \$0 \$5.21,536 \$0 \$0 \$0 \$0 \$0 \$0 \$84,280 0.66%	Builder's risk insurance	0.65%								\$73,434
\$0.00% 0.00% 0.00% 0.00% 0.00% 0.00% 0.00% 0.00% \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	•	Overall								
\$0 \$0 \$0 \$0 \$0 \$0 \$521,536 \$0 \$0 \$0 \$0 \$0 \$0 0.00% \$84,280 0.10% 0.66%	Overhead	3.: P=]1	%00.0	0,00%	%00'0	%00'0		%00°0	%000	
\$521,536 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0 \$0	lef called	0\$	80	0\$	0\$	0\$	\$0	\$0	\$0	\$0
\$521,536 \$0 \$0 \$0 \$0 \$0 \$0 \$ \$ \$ \$ \$ \$ \$ \$ \$ \$	Profit	. 5.00%	0.00%	0.00%	%00,0	\$00.00%	%00.0	0.00%	%00.0	
0.00% \$84,280 0.10% 0.66%	-	521,536	\$0	\$0	\$0	90	\$0	\$0	0 €	\$521,536
\$84,280 0.10% 0.66%		%00.0								\$0
0.10% 0.66%		\$84,280								\$84,280
0.66%	Owner's Protective	0.10%								\$11,297
Cut/Add	New Orleans B.P.	0.66%							<u></u>	\$74,563
Cut/Add									_	
Cirt/Add	14 T									\$11,297,497
Sp. Jano	Cut/Add									0\$

Pro-Serv estimating LLC 444 Red Maple Dr Mandeville LA, LA 70002 Phone: 504888-9433 Fax: 504888-6997

Estimate Detail

Estimate File: Priestley School New Educational Bldg.est - Priestley School existing Building, New Orleans

Estimator: Primary Project City: 49400 SF Estimate UM:Imperial

Sort Sequences: 1. Divisions 2. Not Used 3. Not Used 4. Not Used 4. Not Used

Report DOES NOT include Taxes & Insurance or Indirect Costs.

7:39:32AM	•			j				5/3/2012
		LIND	UNIT COSTS		TOTAL COSTS			
Code Description	Quantity	Labor Material	Sub Equipt	Labor	Material Sub	Equipt	Total Unit \$	Item Total \$
01 General requirements						•		
1310.110 General Conditions	9.00 MO	00.00	40,000.00	\$0.00	360,000.00	00	40,000.00	360,000
Total General requirements					\$360,000	00	1	\$360,000
02 Sitework								
2000.000 Demolition (Selective) 46	49,400.00 SQFT	0.00	0.50	\$0.00	24,700.00	00	0.50	24,700
2200.000 Site Package 46	49,400.00 SQFT	0.00	6.00	\$0.00	296,400.00	00	0.00	296,400
Total Sitework					\$321,100	00		\$321,100
03 Concrete								
refe	49,400.00 SQFT	0.00	17.00	\$0.00	839,800,00	00.	17.00	839,800
Total Concrete					008'628\$	8	1	\$839,800
04 Masonry								
Auc	49,400.00 SQFT	0.00	14.00	\$0.00	691,600,00	00	14.00	691,600
Total Masonry					\$691,600	8		\$691,600
05 Metals								
ructural (Misc)	49,400.00 SQFT	0.00	24.00	\$0.00	1,185,600.00	00	24.00	1,185,600
Total Metals					\$1,185,600	8	!	\$1,185,600
06 Wood and plastics								
6200.000 Rough Carpentry (wood frame) 45	49,400.00 SQFT	0.00	1.00	\$0.00	49,400.00	00:	1.00	49,400
6400.000 Finish carpentry 46	49,400.00 SQFT	00.0	4.00	\$0.00	197,600.00	00:	4.00	197,600
Total Wood and plastics					\$247,000	90		\$247,000
07 Thermal and moisture protection	.:							
7120.000 Waterproofing	49,400.00 SQFT	0.00	2.00	\$0.00	98,800.00	00:	2.00	98,800
	49,400.00 SQFT	0.00	2.00	\$0.00	98,800,00	0	2.00	98,800
7520.000 Roofing (modified bit)	16,000.00 SQFT	0.00	13.00	\$0.00	208,000.00	00	13.00	208,000

Sort Sequences: 1. Divisions 2. Not Used 3. Not Used 4. Not Used

Estimator: Primary Project Qty. 49400 SF Estimate UM:Imperial


\$600.00 \$600.00 \$600.00 \$600.00 \$600.00 \$600.00 \$600.00 \$600.00 \$600.00 \$600.00 \$600.00 \$600.00 \$600.00 \$600.00 \$600.00 \$600.00 \$600.00 \$600.00	7:39:32AM	Estimate File: Pries	Estimate File: Priestley School New Educational Bldg.est - Priestley School existing Building	ucational Bldg.est -	Priestley Schoo	ol existing B	Buiplin			5/3/2012
Fames Hardware A-4-00 to SGPT A-00 to SGPT			UNIT (Labor Material	COSTS Equipt	Labor	TOTAL	Sub	Equipt	Total	ltem
Flames Hardware	Total Thermal and moisture protection	Quantity			49	49	\$	44	Unit \$	Total \$
Former Hartware 49,400.00 SQFT 0.00 17.00 0.00										200,000
s Giazzing 49,400.00 SGPT 0.00 12.00 \$0.00 substage 49,400.00 SGPT 0.00 12.00 \$0.00 substage 49,400.00 SGPT 0.00 12.00 \$0.00 package 49,400.00 SGPT 0.00 7.00 \$0.00 package 49,400.00 SGPT 0.00 7.00 \$0.00 package 49,400.00 SGPT 0.00 12.00 \$0.00 package 49,400.00 SGPT 0.00 12.00 \$0.00 shing package 49,400.00 SGPT 0.00 12.00 \$0.00 struction 49,400.00 SGPT 0.00 12.00 \$0.00 <tr< td=""><td>8000 000 Door Frame, Hardware</td><td>49 400 00 SOFT</td><td></td><td></td><td>6</td><td></td><td>000</td><td></td><td></td><td>200</td></tr<>	8000 000 Door Frame, Hardware	49 400 00 SOFT			6		000			200
S Clearing 49,400.00 SQFT 0.00 12.00 \$0.00 If backage 49,400.00 SQFT 0.00 3.00 \$0.00 package 49,400.00 SQFT 0.00 4 00 \$0.00 package 49,400.00 SQFT 0.00 5.00 \$0.00 package 49,400.00 SQFT 0.00 2.00 \$0.00 package 49,400.00 SQFT 0.00 2.00 \$0.00 package 49,400.00 SQFT 0.00 2.00 \$0.00 struction 49,400.00 SQFT 0.00 2.00 \$0.00 struction 49,400.00 SQFT 0.00 2.00 \$0.00 systems 49,400.00 SQFT 0.00 2.00 \$0.00		- 190 oo: 00t '0t	 	5 F	00.00		197,000,000		4.00	000,761
	8800.000 Glass & Glazing	49,400.00 SQFT	0.00	12.00	\$0.00		592,800.00		12.00	592,800
Section Sect	Total Doors and windows						\$790,400			\$790,400
wildsage 49,400 00 SQFT 0.00 12.00 \$0.00 sites 49,400 00 SQFT 0.00 3.00 \$0.00 sites 49,400 00 SQFT 0.00 7.00 \$0.00 package 49,400 00 SQFT 0.00 12.00 \$0.00 sites 49,400 00 SQFT 0.00 12.00 \$0.00 sites package 49,400 00 SQFT 0.00 12.00 \$0.00 site site 0.00 12.00 \$0.00 \$0.00 site site \$0.00 \$0.00 \$0.00 \$0.00 site site \$0.00 \$0.00 \$0.00 \$0.00 site site \$0.00 \$0.00 \$0.00 \$0.00 systems 49,400.00 SQFT 0.00 2.66 \$0.00 \$0.00 systems 49,400.00 SQFT 0.00 2.66 \$0.00 \$0.00 systems systems 3.50 \$0.00 \$0.00 systems	09 Finishes									
ackage 49,400.00 SQFT 0.00 4.00 \$5.0	9250.000 Drywall Package	49,400.00 SQFT	0.00	12.00	\$0.00		592,800.00		12.00	592,800
100 100	9300.000 Tile package	49,400.00 SQFT	00.0	3.00	\$0.00		148,200.00		3.00	148,200
Package	9510.000 Acoustics	49,400.00 SQFT	00.00	4.00	\$0.00		197,600.00		4.00	197,600
## Statement Prockage	9600.000 Flooring package	49,400.00 SQFT	0.00	2.00	\$0.00		345,800.00		7.00	345,800
### package	9900.000 Paint package	49,400.00 SQFT	00.00	2.00	\$0.00		247,000.00		5.00	247,000
### package ### 49,400.00 SQFT	Total Finishes					1	\$1,531,400			\$1,531,400
State Stat	10 Specialties									
### Package	10000.000 Specialties package	49,400.00 SQFT	00.00	2.00	\$0.00		98,800.00		2.00	98,800
The fackage	Total Specialties						\$98,800			\$98,800
t	11 Equipment									
t	11000.000 Equipment Package	49,400.00 SQFT	0.00	12.00	\$0.00		592,800.00		12.00	592,800
Struction	Tofal Equipment						\$592,800			\$592,800
gs 49,400.00 SQFT 0.00 \$0.00 \$0.00 struction 49,400.00 SQFT 0.00 \$0.00 \$0.00 systems 49,400.00 SQFT 0.00 2.65 \$0.00 systems 49,400.00 SQFT 0.00 \$0.00 rotection 49,400.00 SQFT 0.00 \$0.00 sing Package 49,400.00 SQFT 0.00 \$0.00	12 Furnishings									
ys struction \$0.00 \$0.00 \$0.00 systems 49,400.00 SQFT 0.00 2.65 \$0.00 ystems 49,400.00 SQFT 0.00 2.65 \$0.00 g systems 49,400.00 SQFT 0.00 \$0.00 \$0.00 ing Package 49,400.00 SQFT 0.00 \$0.00 \$0.00	12000.000 Furnishing package	49,400.00 SQFT	00.00	3.00	\$0.00		148,200.00		3.00	148,200
struction 49,400.00 SQFT 0.00 2.00 \$0.00 al construction 49,400.00 SQFT 0.00 2.65 \$0.00 systems 49,400.00 SQFT 0.00 2.65 \$0.00 rotection 49,400.00 SQFT 0.00 \$0.00 rotection 49,400.00 SQFT 0.00 \$0.00	Total Furnishings						\$148,200			\$148,200
air construction 49,400.00 SQFT 0.00 \$0.00 \$0.00 systems 49,400.00 SQFT 0.00 2.65 \$0.00 systems 49,400.00 SQFT 0.00 3.50 \$0.00 rotection 49,400.00 SQFT 0.00 \$0.00 sing Package 49,400.00 SQFT 0.00 \$0.00	13 Special construction									
systems \$9.400.00 \$QFT 0.00 2 65 \$0.00 g systems 49,400.00 \$QFT 0.00 3.50 \$0.00 rotection 49,400.00 \$QFT 0.00 \$0.00 \$0.00	13000.000 Special construction	49,400.00 SQFT	00.0	2.00	\$0.00		98,800.00		2.00	98,800
systems 49,400.00 SQFT 0.00 2 65 \$0.00 g systems volection 3.50 \$0.00 rotection 49,400.00 SQFT 0.00 \$0.00 sing Package 49,400.00 SQFT 0.00 \$0.00	Total Special construction						\$98,800			\$98,800
g systems 49,400.00 SQFT 0.00 2 65 \$0.00 g systems \$0.00 \$0.00 \$0.00 rotection 49,400.00 SQFT 0.00 \$0.00 sing Package 49,400.00 SQFT 0.00 \$0.00	14 Conveying systems									
g systems rotection 49,400,00 SQFT 0.00 3.50 \$0.00 aing Package 48,400,00 SQFT 0.00 \$0.00	14200.000 Elevator Package	49,400.00 SQFT	0.00	2.65	\$0.00		130,910.00		2.65	130,910
rotection 49,400.00 SQFT 0.00 3.50 \$0.00 ning Package 49,400.00 SQFT 0.00 7.00 \$0.00	Total Conveying systems						\$130,910			\$130,910
49,400.00 SQFT 0.00 3.50 \$0.00 49,400.00 SQFT 0.00 7.00 \$0.00	15 Mechanical									
49,400.00 SQFT 0.00 7.00 \$0.00	15300.000 Fire Protection	49,400.00 SQFT	00.00	3.50	\$0.00		172,900.00		3.50	172,900
	15400.000 Plumbing Package	49,400.00 SQFT	00.0	2.00	\$0.00		345,800.00		7.00	345,800

Sort Sequences: 1. Divisions 2. Not Used 3. Not Used 4. Not Used


Estimator: Primary Project Qty: 49400 SF Estimate UM:Imperial

7:39:32AM	Estimate File: Pries	stley School New Edu	ıcational Bldg.est - Pri	Estimate File: Priestley School New Educational Bldg.est - Priestley School existing Building	Building		5/3/2012
) LINO	UNIT COSTS	TOTAL	TOTAL COSTS		
rem Code Description	Quantity	Labor Material \$	Sub Equipt	Labor Material	Sub Equipt	Total Unit \$	Item Total \$
15700.000 Mechanical Package	49,400.00 SQFT	0.00	30.00	\$0.00	1,482,000 00	30.00	1,482,000
Total Mechanical					\$2,000,700		\$2,000,700
16 Electrical							
16000.000 Electrical	49,400.00 SQFT	00.0	20.00	\$0.00	00.000,086	20.00	988,000
Total Electrical				1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	\$988,000		\$988,000
ESTIMATE TOTALS					\$10,430,710	-	\$10.430.710

Building Sections Scale: 1/16"= 1'-0"



Longitudinal Section Scale: 1/16"= 1'-0"



Transverse Section Scale: 1/16"= 1'-0"

SITE & BUILDING ASSESSMENT

Waggonner & Ball Architects

Waggonner & Ball Architects



Building Elevations Scale: 1/16"= 1'-0"

Southwest Elevation Scale: 1/16"= 1'-0"




Northwest Elevation Scale: 1/16"= 1'-0"

SITE & BUILDING ASSESSMENT Waggonner & Ball Architects

Waggonner & Ball Architects



Northeast Elevation Scale: 1/16"= 1'-0"



Southeast Elevation Scale: 1/16"= 1'-0"