Results for Vessel: STRETCH DUCK 07

Vessel Information:

Vessel Name: STRETCH DUCK 07

Primary Vessel Number: CG248292 (Coast Guard Number)
Hull Identification Number: N/A

Manufacturer Hull Number: 35311427 IMO Number: N/A

Vessel Flag: UNITED STATES Vessel Call Sign: N/A

Service Information:

Vessel Particulars:

Service: Passenger (Inspected)

Length: 33.00 ft Breadth: N/A Depth: N/A Build Year: 1944 Alternate VINs: N/A

Tonnage Information: Cargo Authority: N/A

Tonnage:

• 4 - Simplified, Net Ton

• 4 - Simplified, Gross Ton

Service Status: Active Out Of Service Date: N/A

Last Removed From Service By: N/A

Vessel Documents and Certifications

Document	Agency	Date Issued	Expiration Date
Certificate of Inspection	USCG	February 7,2017	February 7,2022
Certificate of Inspection - Amended	USCG	February 7,2017	February 7,2022
Certificate of Inspection	N/A	February 7,2012	February 7,2017
Certificate of Inspection - Amended	N/A	February 7,2012	February 7,2017
Certificate of Inspection - Amended	N/A	February 7,2012	February 7,2017
Certificate of Inspection	N/A	November 3,2010	November 3,2015
Stability Letter	N/A	March 19,2009	
Certificate of Inspection	N/A	February 23,2006	February 23,2011
Certificate of Inspection - Amended	N/A	February 23,2006	February 23,2011
Certificate of Inspection	N/A	March 15,2001	March 15,2006

Summary of Coast Guard Contacts

To View Contact Data From: 07/26/2013 **To:** 07/26/2018 (MM/DD/YYYY)

Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type			
6353715	Not Associated with a Case	St. Louis, Missouri	Monday, February 12, 2018	Vessel Inspection			
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type			
6302753	Not Associated with a Case	St. Louis, Missouri	Monday, November 27, 2017	Vessel Inspection			
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type			
6068142	Not Associated with a Case	St. Louis, Missouri	Monday, January 9, 2017	Vessel Inspection			
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type			
5790668	Not Associated with a Case	St. Louis, Missouri	Monday, January 4, 2016	Vessel Inspection			
	Deficiency Information						
	System	SubSystem	Cause				
	Fire Fighting	Fixed Fire Detection System	Not Available				
	Description of Deficiency						
Resolved Deficiency	Heat detectors were inoperable. Provide proof of proper operation of heat detecting system.						
	Due Date	Resolved	Resolved Date				
	Wednesday, January 13, 2016	True	Wednesday, January 13, 2016				
	Resolution Description						
	Problem was traced to a missing 10 amp fuse. Fuse was replaced and system verified operational by attending marine inspector.						

Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type			
5147529	729271	WASHINGTON, District of Columbia	Saturday, June 6, 2015	Incident Investigation			
	Incident Information Role	nuglty.		-			
,	Involved in a Marine Cas	sually					
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type			
5039564	Not Associated with a Case	St. Louis, Missouri	Monday, December 15, 2014	Vessel Inspection			
	Deficiency Information	•					
	System	SubSystem	Cause				
	Engineering	Bilge Water Management System	Improper Installation				
	Description of Deficien	су					
Resolved Deficiency	Due to the small inside diameter of bilge discharge piping, approximately 5/8", bilge pumps are not pumping to needed capacities.						
	Due Date	Resolved	Resolved Date				
	Saturday, February 7, 2015	True	Tuesday, April 7, 2015				
	Resolution Description						
	Keel cooler thru hulls were relocated to the seachest and patches in the hull plating were tested.						
	Deficiency Information		_				
	System	SubSystem	Cause				
	Construction/Loadline	Hull	Improper/Lack of Mainter	nance			
	Description of Deficiency						
Resolved Deficiency	While conducting in water test of vessel, water leakage was noticed in stbd, fwd, wheel well. It was determined that leakage was caused by RTV/sealant failure. In process of removing RTV with a torch, a 3/16" X 3" hole was cut into the hull accidentally. See photos in Docs/Certs.						
	Due Date	Resolved	Resolved Date				
	Saturday, February 7, 2015	True	Thursday, February 12, 2015				
	Resolution Description						
	Recieved and reviewed						
	Operation Control Information						
	Category Type	Control Type	Initiating Port				
**Operational	Safety	No-Sail CG-835	Sector Upper Mississippi	River			
Control**	Date Imposed	Date Removed	Reason Imposed				
	Wednesday, January 7, 2015	Tuesday, April 7, 2015	Identified Hazardous/Unsafe Condition				
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type			
4922313	Not Associated with a Case	St. Louis, Missouri	Monday, July 14, 2014	Vessel Inspection			
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type			
4797685	Not Associated with a Case	St. Louis, Missouri	Monday, February 10, 2014	Vessel Inspection			
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type			
4796074	Not Associated with a Case	St. Louis, Missouri	Friday, February 7, 2014	Vessel Inspection			
Activity Number	Case Number	Responsible Unit's USCG Zone/Port	Incident Date	Activity Type			
	Not Associated with a		Tuesday, September 17, 2013				