AUSTIN FIRE DEPARTMENT

Property Inspection Report

505 Barton Springs Road, 2nd Floor
Austin, Texas 78704

Phone: (512) 974-0160
Fax: (512) 974-0162

Business Name OAK HOLLOW / OFFICE
Address 7201 WOOD HOLLOW DR Office
AUSTIN, TX. 78731
Fixed Property Use 599 Business Office

DATE/TIME	Inspection Type	UNIT	INSPECTOR
03/03/2005	**In-service Company Inspections**	E19A	DANIEL FIERO

Inspection Event Items:

Inspection Status: Unsatisfactory

97- Private Hydrants require testing.

4I - Tree lighting in pool area near bldg. #5 requires repair-exposed wires.

4I - Underwater pool light in pool near bldg. #5 requires servicing-light is laying in the bottom of the pool with wires still attached.

97a Missing Code, see comments

Inspection Status: Unsatisfactory

97- Private Hydrants require testing.

4I - Tree lighting in pool area near bldg. #5 requires repair-exposed wires.

4I - Underwater pool light in pool near bldg. #5 requires servicing-light is laying in the bottom of the pool with wires still attached.

4D Electrical boxes lack covers as required.

Inspection Status: Unsatisfactory

97- Private Hydrants require testing.

4I - Tree lighting in pool area near bldg. #5 requires repair-exposed wires.

4I - Underwater pool light in pool near bldg. #5 requires servicing-light is laying in the bottom of the pool with wires still attached.

4I Wiring not maintained in good condition

Inspection Status: Unsatisfactory

97- Private Hydrants require testing.

4I - Tree lighting in pool area near bldg. #5 requires repair-exposed wires.

4I - Underwater pool light in pool near bldg. #5 requires servicing-light is laying in the bottom of the pool with wires still attached.

1F Combustible materials stored in boiler room, mechanical room, or electrical room.