



U.S. DOT# 113378 has no current for-hire operating authority with FMCSA.

LATTIMORE MATERIALS CORP

DBA: LATTIMORE MATERIALS OR COLORADO RIVER CONCRETE

U.S. DOT#: 113378
Address: 15900 DOOLEY RD
ADDISON, TX 75001
Number of Vehicles: 387
Number of Drivers: 328
Number of Inspections: 127

Safety Rating & OOS Rates

(As of 02/13/2020 updated daily
from [SAFER](#))

SATISFACTORY
(Rating Date: 07/07/2010)

Out of Service Rates

Type	OOS %	National Avg %
Vehicle	26.5	20.7
Driver	1.6	5.5
Hazmat	0.0	4.5

Licensing and Insurance

(As of 02/13/2020 updated hourly
from [L&I](#))

Active For-Hire Authority	
Type	Yes/No MC#/MX#
Property	No
Passenger	No
Household Goods	No
Broker	No

BASIC Status (Public Property Carrier View) ?

Behavior Analysis & Safety Improvement Categories (BASICS)

Based on a 24-month record ending January 31, 2020

Unsafe Driving	Crash Indicator	Hours-of-Service Compliance	Vehicle Maintenance	Controlled Substances and Alcohol	Not Public Hazardous Materials Compliance	Driver Fitness

Select a BASIC icon above to get details, or view your [Complete SMS Profile](#).

BASIC: Vehicle Maintenance

On-Road Performance

Measure: 6.42 ?


Safety Event Group: 101-500 relevant vehicle inspections

Investigation Results

No Acute/Critical Violations Discovered

CARRIER MEASURE OVER TIME


This graph displays a carrier's measure based on 24 months of on-road performance. Zero indicates the best performance. To see how the measure is calculated [click here](#). To see how the measure relates to percentile [click here](#). [Expand](#) for more information.



	Aug 30 2019	Sep 27 2019	Oct 25 2019	Nov 29 2019	Dec 27 2019	Jan 31 2020
Status	Active	Active	Active	Active	Active	Active
BASIC Trends Version	3.0.10	3.0.10	3.0.10	3.0.10	3.0.10	3.0.10
Investigation Results						
On-Road Performance Detail						
Measure	6.26	6.13	6.40	6.44	6.46	6.42
Safety Event Group	101-500 relevant vehicle inspections	101-500 relevant vehicle inspections	101-500 relevant vehicle inspections	101-500 relevant vehicle inspections	101-500 relevant vehicle inspections	101-500 relevant vehicle inspections
Vehicle Inspections	113	115	120	116	111	114
with Vehicle Maint. Violations	84	86	89	86	83	84
without Vehicle Maint. Violations	29	29	31	30	28	30
Vehicle Maint. Violations	216	218	230	223	215	221

INSPECTION RESULTS

The graph below displays the number of inspections that the carrier has received for a selected period of time, with or without violations for this BASIC. [Expand](#) for more information.



VIOLATION SUMMARY

Vehicle Maint. Violations: 221

Violations	Description	# Violations	# OOS Violations	Violation Severity Weight
393.78	Windshield wipers inoperative/defective	31	0	1
393.9	Inoperable Required Lamp	25	1	2
396.5(b)	Oil and/or grease leak	16	0	3
393.55(d)(1)	CMV not equipped with ABS malfunction circuit or signal (Truck-Tractor mfg on/after 3/1/1997; Straight Truck mfg on/after 3/1/1998)	11	0	4
393.95(a)	No/discharged/unsecured fire extinguisher	11	0	2
396.3(a)(1)	Inspection, repair and maintenance of parts & accessories	10	3	2
393.95(b)	No spare fuses as required	9	0	2
393.47(e)	Clamp or Roto type brake out-of-adjustment	8	0	4
396.17(c)	Operating a CMV without proof of a periodic inspection	7	0	4
393.209(e)	Power steering violations	6	0	6
393.100(a)	No or improper load securement	5	5	1
393.45	Brake tubing and hose adequacy	4	4	4
393.53(b)	CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear	4	0	4
393.75(f)(1)	Weight carried exceeds tire load limit	4	4	3
396.3A1T	Tires (general)	4	4	8
393.28	Improper or no wiring protection as required	3	0	3
393.45(b)(2)	Brake hose or tubing chafing and/or kinking	3	2	4
393.75(a)(3)	Tire-flat and/or audible air leak	3	3	8
393.83(g)	Exhaust leak under truck cab and/or sleeper	3	0	1
393.9TS	Inoperative turn signal	3	1	6
396.3A1B	Brakes (general) Explain:	3	0	4
392.9	Driver may not operate a CMV without proper load securement	2	2	1

393.24(b)	Noncompliant fog/driving lamps	2	0	6
393.45(d)	Brake connections with leaks or constrictions	2	0	4
393.47(a)	Inadequate brakes for safe stopping	2	0	4
393.51	No or defective brake warning device	2	0	4
393.55(c)(2)	CMV other than truck-tractor manufactured on or after March 1, 1998 not equipped with an antilock brake system.	2	0	4
393.55(d)(2)	CMV manufactured on/after 3/1/2001 not equipped with ABS malfunction circuit / lamp from towed vehicle in cab.	2	0	4
393.55(d)(3)	No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001	2	0	4
393.55(e)	No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998	2	0	4
393.93(b)	Failure to equip truck with seatbelts	2	0	2
393.95(f)	No / insufficient warning devices	2	0	2
396.3(a)1BOS	BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination	2	2	0
396.3A1BL	Brake system pressure loss	2	2	4
396.5B-HLIW	Hubs - Oil and/or Grease Leaking from hub - inner wheel	2	1	2
396.5B-HLOW	Hubs - oil and/or Grease Leaking from hub - outer wheel	2	0	2
393.11	No or defective lighting devices or reflective material as required	1	0	3
393.11LR	No Lower rear retroreflective sheeting or reflex reflective materials as required for vehicles manufactured after December 1993	1	0	3
393.11TT	Truck-Tractor with No retroreflective sheeting or reflex reflective material on vehicle manufactured after July 1997	1	0	3
393.205(c)	Wheel fasteners loose and/or missing	1	0	2
393.209(a)	Steering wheel not secured/broken	1	0	6
393.209(c)	Loose steering column	1	1	6
393.209(d)	Steering system components worn, welded, or missing	1	0	6
393.25(f)	Stop lamp violations	1	0	6
393.45B2PC	Brake Hose or Tubing Chafing and/or Kinking - Connection to Power Unit	1	0	4
393.45B2UV	Brake Hose or Tubing Chafing and/or Kinking Under Vehicle	1	0	4
393.45DLUV	Brake Connections with Leaks Under Vehicle	1	0	4
393.48(a)	Inoperative/defective brakes	1	0	4
393.55(c)(1)	Truck Tractor manufactured on or after March 1, 1997 not equipped with an antilock brake system.	1	0	4
393.75G-LOAD	Weight carried exceeds tire load limit	1	1	3
393.79	Defroster / Defogger inoperative	1	0	1
393.83(b)	Exhaust discharge fuel tank/filler tube	1	0	1
393.9H	Inoperable head lamps	1	0	6
393.9T	Inoperable tail lamp	1	0	6

INSPECTION HISTORY

Vehicle Inspections: 114

Report			Vehicle			Measure = Sum of the Total Weight (TotW) Sum of the Time Weight (TiW)		
Inspection Date	Number	State	Plate Number	Plate State	Type	Severity Weight (SW)	Time Weight (TiW)	Total Weight (TotW)
1/8/2020	TX5N4A9DKJ1Q	TX	CWC2416	TX	Straight Truck	5	3	15
Violation: 396.17(c) Operating a CMV without proof of a periodic inspection						4		
Violation: 393.78 Windshield wipers inoperative/defective						1		

Only the 1000 most recent inspections are included in this print view.

Sum of measure weights	721	194	1,247
------------------------	-----	-----	-------

Report			Vehicle			Measure =		
						Sum of the Total Weight (TotW)		
						Sum of the Time Weight (TiW)		
Inspection Date	Number	State	Plate Number	Plate State	Type	Severity Weight (SW)	Time Weight (TiW)	Total Weight (TotW)
Sum of Violation Weight => Inspection Severity Weight (SW)						5		
1/8/2020	TX5N4C9DKJ1R	TX	LMW3237	TX	Straight Truck	15	3	45
Violation:	393.53(b) CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear					4		
Violation:	393.55(d)(1) CMV not equipped with ABS malfunction circuit or signal (Truck-Tractor mfg on/after 3/1/1997; Straight Truck mfg on/after 3/1/1998)					4		
Violation:	393.47(e) Clamp or Roto type brake out-of-adjustment					4		
Violation:	393.95(b) No spare fuses as required					2		
Violation:	393.78 Windshield wipers inoperative/defective					1		
Sum of Violation Weight => Inspection Severity Weight (SW)						15		
1/8/2020	TX5N4C9DMR0N	TX	AR26932	TX	Straight Truck	17	3	51
Violation:	393.47(e) Clamp or Roto type brake out-of-adjustment					4		
Violation:	396.3(a)1BOS BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination (OOS)					0 + 2 (OOS)		
Violation:	396.3(a)(1) Inspection, repair and maintenance of parts & accessories (OOS)					2 + 2 (OOS)		
Violation:	393.95(a) No/discharged/unsecured fire extinguisher					2		
Violation:	393.78 Windshield wipers inoperative/defective					1		
Violation:	393.53(b) CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear					4		
Sum of Violation Weight => Inspection Severity Weight (SW)						17		
12/23/2019	TX5MO99DFYTR	TX	DZH2670	TX	Straight Truck	0	3	0
12/19/2019	TX5MKD0XNTAS	TX	LKJ8940	TX	Straight Truck	0	3	0
12/19/2019	TX5MKB0VJY0W	TX	CFL9843	TX	Straight Truck	10	3	30
Violation:	396.3A1T Tires (general) (OOS)					8 + 2 (OOS)		
12/10/2019	TX5MB89DGI1U	TX	GWH2125	TX	Straight Truck	16	3	48
Violation:	393.75(a)(3) Tire-flat and/or audible air leak (OOS)					8 + 2 (OOS)		
Violation:	393.78 Windshield wipers inoperative/defective					1		
Violation:	393.75(f)(1) Weight carried exceeds tire load limit (OOS)					3 + 2 (OOS)		
Sum of Violation Weight => Inspection Severity Weight (SW)						16		
12/9/2019	TX5MAC9DMT2P	TX	CFL9843	TX	Straight Truck	16	3	48
Violation:	393.209(e) Power steering violations					6		
Violation:	393.83(g) Exhaust leak under truck cab and/or sleeper					1		
Violation:	393.9TS Inoperative turn signal					6		
Violation:	396.5(b) Oil and/or grease leak					3		
Sum of Violation Weight => Inspection Severity Weight (SW)						16		
12/6/2019	TX5M759DBF1Y	TX	KGP8070	TX	Straight Truck	0	3	0
11/20/2019	TX5LR79DFYT2	TX	KMB0681	TX	Straight Truck	2	3	6
Violation:	393.205(c) Wheel fasteners loose and/or missing					2		
10/24/2019	TX5L0G0XUR1S	TX	CCG6519	TX	Straight Truck	9	3	27
Violation:	393.209(e) Power steering violations					6		
Violation:	396.5(b) Oil and/or grease leak					3		
Sum of Violation Weight => Inspection Severity Weight (SW)						9		
10/16/2019	TX5KS79DMPIM	TX	BCH0411	TX	Straight Truck	5	3	15
Violation:	393.78 Windshield wipers inoperative/defective					1		
Only the 1000 most recent inspections are included in this print view.								
Sum of measure weights						721	194	1,247

Report			Vehicle			Measure =		
						Sum of the Total Weight (TotW)		
						Sum of the Time Weight (TiW)		
Inspection Date	Number	State	Plate Number	Plate State	Type	Severity Weight (SW)	Time Weight (TiW)	Total Weight (TotW)
Violation: 393.55(c)(2) CMV other than truck-tractor manufactured on or after March 1, 1998 not equipped with an antilock brake system.						4		
Sum of Violation Weight => Inspection Severity Weight (SW)						5		
10/16/2019	TX5KSC0XK07B	TX	1M00897	TX	Truck Tractor	16	3	48
Violation: 393.9TS Inoperative turn signal (OOS)						6 + 2 (OOS)		
Violation: 393.55(c)(1) Truck Tractor manufactured on or after March 1, 1997 not equipped with an antilock brake system.						4		
Violation: 393.55(e) No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998						4		
Sum of Violation Weight => Inspection Severity Weight (SW)						16		
10/10/2019	TX5KM89DFYRY	TX	LJX6428	TX	Straight Truck	0	3	0
10/7/2019	TX5KJ89DLWQU	TX	AP74753	TX	Straight Truck	3	3	9
Violation: 393.95(b) No spare fuses as required						2		
Violation: 393.78 Windshield wipers inoperative/defective						1		
Sum of Violation Weight => Inspection Severity Weight (SW)						3		
9/27/2019	OKB509152221	OK	9391AE	TX	Straight Truck	0	3	0
9/25/2019	TX5K779DGIIB	TX	GWH2125	TX	Straight Truck	14	3	42
Violation: 393.9H Inoperable head lamps						6		
Violation: 393.9 Inoperable Required Lamp						2		
Violation: 393.78 Windshield wipers inoperative/defective						1		
Violation: 393.75(f)(1) Weight carried exceeds tire load limit (OOS)						3 + 2 (OOS)		
Sum of Violation Weight => Inspection Severity Weight (SW)						14		
9/23/2019	TX5K5D9DIZHW	TX	LMW3232	TX	Straight Truck	10	3	30
Violation: 393.100(a) No or improper load securement (OOS)						1 + 2 (OOS)		
Violation: 393.9 Inoperable Required Lamp						2		
Violation: 396.17(c) Operating a CMV without proof of a periodic inspection						4		
Violation: 393.78 Windshield wipers inoperative/defective						1		
Sum of Violation Weight => Inspection Severity Weight (SW)						10		
9/19/2019	TX5K179DHT0U	TX	LRF4417	TX	Straight Truck	2	3	6
Violation: 393.9 Inoperable Required Lamp						2		
9/13/2019	TX5JVE0VCIOX	TX	CCG6519	TX	Straight Truck	1	3	3
Violation: 393.78 Windshield wipers inoperative/defective						1		
9/9/2019	TX5JRF0XJGP6	TX	CHJ2238	TX	Straight Truck	3	3	9
Violation: 396.5(b) Oil and/or grease leak						3		
8/7/2019	TX5IU79DGIGA	TX	DTP9904	TX	Straight Truck	9	3	27
Violation: 393.75(f)(1) Weight carried exceeds tire load limit (OOS)						3 + 2 (OOS)		
Violation: 393.55(d)(1) CMV not equipped with ABS malfunction circuit or signal (Truck-Tractor mfg on/after 3/1/1997; Straight Truck mfg on/after 3/1/1998)						4		
Sum of Violation Weight => Inspection Severity Weight (SW)						9		
8/6/2019	TX5IT99DGIG7	TX	DTP9903	TX	Straight Truck	3	3	9
Violation: 393.9 Inoperable Required Lamp						2		
Violation: 393.78 Windshield wipers inoperative/defective						1		
Sum of Violation Weight => Inspection Severity Weight (SW)						3		

Only the 1000 most recent inspections are included in this print view.

Sum of measure weights 721 194 1,247

Report			Vehicle			Measure =		
						Sum of the Total Weight (TotW)		
						Sum of the Time Weight (TiW)		
Inspection Date	Number	State	Plate Number	Plate State	Type	Severity Weight (SW)	Time Weight (TiW)	Total Weight (TotW)
8/5/2019	TX5ISB9DKWZR	TX	FGV2836	TX	Straight Truck	1	3	3
Violation: 393.78 Windshield wipers inoperative/defective						1		
8/5/2019	TX5IS89DFYPE	TX	AW17028	TX	Straight Truck	0	3	0
7/29/2019	TX5IL99DFYOT	TX	LJX6428	TX	Straight Truck	0	2	0
7/24/2019	TX5IGB9DBF91	TX	BCH0405	TX	Straight Truck	25	2	50
Violation: 393.78 Windshield wipers inoperative/defective						1		
Violation: 396.3A1B Brakes (general) Explain:						4		
Violation: 396.3A1BL Brake system pressure loss (OOS)						4 + 2 (OOS)		
Violation: 396.3A1T Tires (general) (OOS)						8 + 2 (OOS)		
Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories						2		
Violation: 393.9 Inoperable Required Lamp						2		
Sum of Violation Weight => Inspection Severity Weight (SW)						25		
7/16/2019	TX5I879DGIFQ	TX	DTP9904	TX	Straight Truck	14	2	28
Violation: 393.55(d)(1) CMV not equipped with ABS malfunction circuit or signal (Truck-Tractor mfg on/after 3/1/1997; Straight Truck mfg on/after 3/1/1998)						4		
Violation: 393.75(a)(3) Tire-flat and/or audible air leak (OOS)						8 + 2 (OOS)		
Sum of Violation Weight => Inspection Severity Weight (SW)						14		
7/12/2019	TX5I4D9DMQ9U	TX	LRW9325	TX	Straight Truck	0	2	0
7/10/2019	TX5I269DKF32	TX	R151024	TX	Truck Tractor	14	2	28
Violation: 396.5B-HLIW Hubs - Oil and/or Grease Leaking from hub - inner wheel (OOS)						2 + 2 (OOS)		
Violation: 393.47(a) Inadequate brakes for safe stopping						4		
Violation: 393.209(d) Steering system components worn, welded, or missing						6		
Sum of Violation Weight => Inspection Severity Weight (SW)						14		
7/3/2019	TX5HV60VFPYT	TX	1M00894	TX	Truck Tractor	3	2	6
Violation: 393.100(a) No or improper load securement (OOS)						1 + 2 (OOS)		
7/3/2019	TX5HV80KFG09	TX	LRF4777	TX	Straight Truck	7	2	14
Violation: 393.100(a) No or improper load securement (OOS)						1 + 2 (OOS)		
Violation: 396.3A1B Brakes (general) Explain:						4		
Sum of Violation Weight => Inspection Severity Weight (SW)						7		
7/3/2019	TX5HVA0KFG0B	TX	LRF4799	TX	Straight Truck	1	2	2
Violation: 393.78 Windshield wipers inoperative/defective						1		
7/2/2019	TX5HU99DGIEU	TX	BCH0581	TX	Straight Truck	12	2	24
Violation: 393.55(d)(1) CMV not equipped with ABS malfunction circuit or signal (Truck-Tractor mfg on/after 3/1/1997; Straight Truck mfg on/after 3/1/1998)						4		
Violation: 393.78 Windshield wipers inoperative/defective						1		
Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories						2		
Violation: 396.5(b) Oil and/or grease leak						3		
Violation: 393.95(a) No/discharged/unsecured fire extinguisher						2		
Sum of Violation Weight => Inspection Severity Weight (SW)						12		
7/2/2019	TX5HUC9DGIEX	TX	BGV8068	TX	Straight Truck	5	2	10
Violation: 393.78 Windshield wipers inoperative/defective						1		
Only the 1000 most recent inspections are included in this print view.								
Sum of measure weights						721	194	1,247

Report			Vehicle			Measure =		
						Sum of the Total Weight (TotW)		
						Sum of the Time Weight (TiW)		
Inspection Date	Number	State	Plate Number	Plate State	Type	Severity Weight (SW)	Time Weight (TiW)	Total Weight (TotW)
Violation: 393.55(d)(1) CMV not equipped with ABS malfunction circuit or signal (Truck-Tractor mfg on/after 3/1/1997; Straight Truck mfg on/after 3/1/1998)						4		
Sum of Violation Weight => Inspection Severity Weight (SW)						5		
7/1/2019	TX5HT69DGIEP	TX	AD96248	TX	Straight Truck	23	2	46
Violation: 393.78 Windshield wipers inoperative/defective						1		
Violation: 393.45 Brake tubing and hose adequacy (OOS)						4 + 2 (OOS)		
Violation: 393.47(e) Clamp or Roto type brake out-of-adjustment						4		
Violation: 393.53(b) CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear						4		
Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories (OOS)						2 + 2 (OOS)		
Violation: 396.3(a)1BOS BRAKES OUT OF SERVICE: The number of defective brakes is equal to or greater than 20 percent of the service brakes on the vehicle or combination (OOS)						0 + 2 (OOS)		
Violation: 396.5B-HLIW Hubs - Oil and/or Grease Leaking from hub - inner wheel						2		
Sum of Violation Weight => Inspection Severity Weight (SW)						23		
7/1/2019	TX5HT89DFYNU	TX	AR26942	TX	Straight Truck	3	2	6
Violation: 393.95(a) No/discharged/unsecured fire extinguisher						2		
Violation: 393.78 Windshield wipers inoperative/defective						1		
Sum of Violation Weight => Inspection Severity Weight (SW)						3		
6/27/2019	TX5HP99DGIEK	TX	AP74763	TX	Straight Truck	18	2	36
Violation: 393.45 Brake tubing and hose adequacy (OOS)						4 + 2 (OOS)		
Violation: 396.5(b) Oil and/or grease leak						3		
Violation: 393.95(b) No spare fuses as required						2		
Violation: 393.9 Inoperable Required Lamp						2		
Violation: 393.78 Windshield wipers inoperative/defective						1		
Violation: 393.47(e) Clamp or Roto type brake out-of-adjustment						4		
Sum of Violation Weight => Inspection Severity Weight (SW)						18		
6/27/2019	TX5HPA9DGIEL	TX	DSF0817	TX	Straight Truck	20	2	40
Violation: 393.55(d)(1) CMV not equipped with ABS malfunction circuit or signal (Truck-Tractor mfg on/after 3/1/1997; Straight Truck mfg on/after 3/1/1998)						4		
Violation: 393.47(e) Clamp or Roto type brake out-of-adjustment						4		
Violation: 393.95(a) No/discharged/unsecured fire extinguisher						2		
Violation: 396.5(b) Oil and/or grease leak						3		
Violation: 396.3A1BL Brake system pressure loss (OOS)						4 + 2 (OOS)		
Violation: 393.78 Windshield wipers inoperative/defective						1		
Sum of Violation Weight => Inspection Severity Weight (SW)						20		
6/27/2019	TX5HPD9DGIEM	TX	BGV8071	TX	Straight Truck	8	2	16
Violation: 393.55(d)(1) CMV not equipped with ABS malfunction circuit or signal (Truck-Tractor mfg on/after 3/1/1997; Straight Truck mfg on/after 3/1/1998)						4		
Violation: 396.5(b) Oil and/or grease leak						3		
Violation: 393.78 Windshield wipers inoperative/defective						1		
Sum of Violation Weight => Inspection Severity Weight (SW)						8		
6/20/2019	TX5HID9DGIDT	TX	DTP9903	TX	Straight Truck	9	2	18
Violation: 393.75(f)(1) Weight carried exceeds tire load limit (OOS)						3 + 2 (OOS)		
Only the 1000 most recent inspections are included in this print view.								
Sum of measure weights						721	194	1,247

Report			Vehicle			Measure =		
						Sum of the Total Weight (TotW)		
						Sum of the Time Weight (TiW)		
Inspection Date	Number	State	Plate Number	Plate State	Type	Severity Weight (SW)	Time Weight (TiW)	Total Weight (TotW)
Violation: 393.55(d)(1) CMV not equipped with ABS malfunction circuit or signal (Truck-Tractor mfg on/after 3/1/1997; Straight Truck mfg on/after 3/1/1998)						4		
Sum of Violation Weight => Inspection Severity Weight (SW)						9		
6/18/2019	TX5HGD9DBOD6	TX	DSF0836	TX	Straight Truck	12	2	24
Violation: 393.9 Inoperable Required Lamp						2		
Violation: 393.55(d)(1) CMV not equipped with ABS malfunction circuit or signal (Truck-Tractor mfg on/after 3/1/1997; Straight Truck mfg on/after 3/1/1998)						4		
Violation: 393.9T Inoperable tail lamp						6		
Sum of Violation Weight => Inspection Severity Weight (SW)						12		
5/28/2019	TX5GVA9DJXWY	TX	DCF4577	TX	Straight Truck	4	2	8
Violation: 393.95(b) No spare fuses as required						2		
Violation: 393.95(a) No/discharged/unsecured fire extinguisher						2		
Sum of Violation Weight => Inspection Severity Weight (SW)						4		
5/28/2019	TX5GVE9DDTDJ	TX	CHJ2240	TX	Straight Truck	3	2	6
Violation: 393.9 Inoperable Required Lamp						2		
Violation: 393.78 Windshield wipers inoperative/defective						1		
Sum of Violation Weight => Inspection Severity Weight (SW)						3		
5/23/2019	TX5GQ99DMPAJ	TX	LRF4423	TX	Straight Truck	0	2	0
5/6/2019	TX5G999DFYL8	TX	KLZ9518	TX	Straight Truck	0	2	0
4/23/2019	TX5FWA0XKTNR	TX	DCT3473	TX	Straight Truck	1	2	2
Violation: 393.83(b) Exhaust discharge fuel tank/filler tube						1		
4/12/2019	TX5FL79DKK0D	TX	JYG2091	TX	Straight Truck	0	2	0
4/10/2019	TX5FJC0MUKR2	TX	BC76268	TX	Straight Truck	0	2	0
4/5/2019	TX5FE90VFPUE	TX	1L53286	TX	Truck Tractor	3	2	6
Violation: 393.100(a) No or improper load securement (OOS)						1 + 2 (OOS)		
4/5/2019	TX5FE99DEF0U	TX	BZR9127	TX	Straight Truck	0	2	0
4/2/2019	TX5FBF0MUKQC	TX	LJX6401	TX	Straight Truck	2	2	4
Violation: 393.9 Inoperable Required Lamp						2		
3/28/2019	TX5F650VAG1L	TX	AD96247	TX	Straight Truck	9	2	18
Violation: 396.5(b) Oil and/or grease leak						3		
Violation: 393.51 No or defective brake warning device						4		
Violation: 393.9 Inoperable Required Lamp						2		
Sum of Violation Weight => Inspection Severity Weight (SW)						9		
3/7/2019	TX5ELH9DBO5S	TX	KMG8819	TX	Straight Truck	4	2	8
Violation: 396.17(c) Operating a CMV without proof of a periodic inspection						4		
2/18/2019	TX5E4F9DBO47	TX	FNR3478	TX	Straight Truck	12	2	24
Violation: 393.11 No or defective lighting devices or reflective material as required						3		
Violation: 396.5B-HLOW Hubs - oil and/or Grease Leaking from hub - outer wheel						2		
Violation: 396.17(c) Operating a CMV without proof of a periodic inspection						4		
Violation: 393.11LR No Lower rear retroreflective sheeting or reflex reflective materials as required for vehicles manufactured after December 1993						3		
Sum of Violation Weight => Inspection Severity Weight (SW)						12		
12/29/2018	TX5CPA9DHT0A	TX	BTG7274	TX	Straight Truck	4	1	4
Violation: 393.47(e) Clamp or Roto type brake out-of-adjustment						4		
12/28/2018	TX5COE0VII4B	TX	HPY2514	TX	Straight Truck	0	1	0
11/30/2018	TX5BW80MUD58	TX	1L13595	TX	Truck Tractor	4	1	4
Only the 1000 most recent inspections are included in this print view.								
Sum of measure weights						721	194	1,247

Report			Vehicle			Measure =		
						Sum of the Total Weight (TotW)		
						Sum of the Time Weight (TiW)		
Inspection Date	Number	State	Plate Number	Plate State	Type	Severity Weight (SW)	Time Weight (TiW)	Total Weight (TotW)
Violation: 393.45B2PC Brake Hose or Tubing Chafing and/or Kinking - Connection to Power Unit						4		
11/30/2018	TX5CFEHQE1JA	TX	BCG9296	TX	Straight Truck	11	1	11
Violation: 393.24(b) Noncompliant fog/driving lamps						6		
Violation: 396.5(b) Oil and/or grease leak						3		
Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories						2		
Sum of Violation Weight => Inspection Severity Weight (SW)						11		
11/27/2018	TX5BT90XKTFZ	TX	AR26932	TX	Straight Truck	0	1	0
11/15/2018	TX5BH99DCO0E	TX	CCG6519	TX	Straight Truck	11	1	11
Violation: 393.95(a) No/discharged/unsecured fire extinguisher						2		
Violation: 393.78 Windshield wipers inoperative/defective						1		
Violation: 393.209(e) Power steering violations						6		
Violation: 393.9 Inoperable Required Lamp						2		
Sum of Violation Weight => Inspection Severity Weight (SW)						11		
11/10/2018	TX5BCK0VJHF1	TX	CHJ2241	TX	Straight Truck	0	1	0
11/1/2018	TX5B399DKSE8	TX	FMT8000	TX	Straight Truck	1	1	1
Violation: 393.78 Windshield wipers inoperative/defective						1		
10/30/2018	TX5B1G9DMP2P	TX	BGZ9651	TX	Straight Truck	8	1	8
Violation: 393.75G-LOAD Weight carried exceeds tire load limit (OOS)						3 + 2 (OOS)		
Violation: 393.78 Windshield wipers inoperative/defective						1		
Violation: 393.95(b) No spare fuses as required						2		
Sum of Violation Weight => Inspection Severity Weight (SW)						8		
10/29/2018	TX5B0D0PETS2	TX	HPY2511	TX	Straight Truck	6	1	6
Violation: 393.45 Brake tubing and hose adequacy (OOS)						4 + 2 (OOS)		
10/24/2018	TX5AV90XKTDA	TX	HPY2587	TX	Straight Truck	0	1	0
10/23/2018	TX5AU70MUKFB	TX	BCH0726	TX	Straight Truck	4	1	4
Violation: 393.9 Inoperable Required Lamp						2		
Violation: 393.95(a) No/discharged/unsecured fire extinguisher						2		
Sum of Violation Weight => Inspection Severity Weight (SW)						4		
10/12/2018	TX5AJ80MUD3B	TX	179918	KS	Truck Tractor	0	1	0
10/11/2018	TX5AI79DCJE8	TX	DTP9900	TX	Straight Truck	12	1	12
Violation: 393.48(a) Inoperative/defective brakes						4		
Violation: 393.209(e) Power steering violations						6		
Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories						2		
Sum of Violation Weight => Inspection Severity Weight (SW)						12		
10/10/2018	TX5AHD0ABRRS	TX	BWY5983	TX	Straight Truck	15	1	15
Violation: 393.209(e) Power steering violations						6		
Violation: 393.209(a) Steering wheel not secured/broken						6		
Violation: 396.5(b) Oil and/or grease leak						3		
Sum of Violation Weight => Inspection Severity Weight (SW)						15		
10/2/2018	TX5A9B9DJE7Y	TX	CHJ1123	TX	Straight Truck	3	1	3
Violation: 393.9 Inoperable Required Lamp						2		
Violation: 393.78 Windshield wipers inoperative/defective						1		
Sum of Violation Weight => Inspection Severity Weight (SW)						3		
9/27/2018	TX5A4B9DBZ1L	TX	HSN9832	TX	Straight Truck	8	1	8
Violation: 393.78 Windshield wipers inoperative/defective						1		
Only the 1000 most recent inspections are included in this print view.								
Sum of measure weights						721	194	1,247

Report			Vehicle			Measure =		
						Sum of the Total Weight (TotW)		
						Sum of the Time Weight (TiW)		
Inspection Date	Number	State	Plate Number	Plate State	Type	Severity Weight (SW)	Time Weight (TiW)	Total Weight (TotW)
Violation: 393.95(f) No / insufficient warning devices						2		
Violation: 393.9 Inoperable Required Lamp						2		
Violation: 392.9 Driver may not operate a CMV without proper load securement (OOS)						1 + 2		
						(OOS)		
Sum of Violation Weight => Inspection Severity Weight (SW)						8		
9/17/2018	TX59UC0XJG0N	TX	JMN9597	TX	Straight Truck	5	1	5
Violation: 396.5(b) Oil and/or grease leak						3		
Violation: 393.9 Inoperable Required Lamp						2		
Sum of Violation Weight => Inspection Severity Weight (SW)						5		
9/5/2018	TX59I80MUKD8	TX	153756	KS	Truck Tractor	0	1	0
8/23/2018	TX595E9DDZ09	TX	BVL4530	TX	Straight Truck	0	1	0
8/15/2018	TX58XB9DHB43	TX	93TCB9	TX	Straight Truck	8	1	8
Violation: 393.55(d)(1) CMV not equipped with ABS malfunction circuit or signal (Truck-Tractor mfg on/after 3/1/1997; Straight Truck mfg on/after 3/1/1998)						4		
Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories (OOS)						2 + 2		
						(OOS)		
Sum of Violation Weight => Inspection Severity Weight (SW)						8		
8/15/2018	TX58XD9DHSV74	TX	CHJ2876	TX	Straight Truck	17	1	17
Violation: 396.5(b) Oil and/or grease leak						3		
Violation: 393.45 Brake tubing and hose adequacy (OOS)						4 + 2		
						(OOS)		
Violation: 393.45B2UV Brake Hose or Tubing Chafing and/or Kinking Under Vehicle						4		
Violation: 393.47(a) Inadequate brakes for safe stopping						4		
Sum of Violation Weight => Inspection Severity Weight (SW)						17		
8/8/2018	TX58Q79DJH6T	TX	BGV8075	TX	Straight Truck	1	1	1
Violation: 393.78 Windshield wipers inoperative/defective						1		
8/6/2018	TX58O70XJG15	TX	JSW3125	TX	Straight Truck	6	1	6
Violation: 393.28 Improper or no wiring protection as required						3		
Violation: 393.78 Windshield wipers inoperative/defective						1		
Violation: 393.9 Inoperable Required Lamp						2		
Sum of Violation Weight => Inspection Severity Weight (SW)						6		
8/1/2018	TX58JF9DBBXD	TX	HSN9834	TX	Straight Truck	4	1	4
Violation: 393.95(a) No/discharged/unsecured fire extinguisher						2		
Violation: 393.93(b) Failure to equip truck with seatbelts						2		
Sum of Violation Weight => Inspection Severity Weight (SW)						4		
7/31/2018	TX58I99DBBX5	TX	DTP9898	TX	Straight Truck	9	1	9
Violation: 393.55(d)(2) CMV manufactured on/after 3/1/2001 not equipped with ABS malfunction circuit / lamp from towed vehicle in cab.						4		
Violation: 393.93(b) Failure to equip truck with seatbelts						2		
Violation: 393.9 Inoperable Required Lamp						2		
Violation: 393.79 Defroster / Defogger inoperative						1		
Sum of Violation Weight => Inspection Severity Weight (SW)						9		
7/24/2018	TX58BD9DIZB8	TX	HPY2587	TX	Straight Truck	4	1	4
Violation: 393.95(f) No / insufficient warning devices						2		
Violation: 393.95(a) No/discharged/unsecured fire extinguisher						2		
Sum of Violation Weight => Inspection Severity Weight (SW)						4		
7/10/2018	TX57XC0MUK96	TX	DSF0811	TX	Straight Truck	0	1	0

Only the 1000 most recent inspections are included in this print view.

Sum of measure weights 721 194 1,247

Report			Vehicle			Measure =		
						Sum of the Total Weight (TotW)		
						Sum of the Time Weight (TiW)		
Inspection Date	Number	State	Plate Number	Plate State	Type	Severity Weight (SW)	Time Weight (TiW)	Total Weight (TotW)
6/26/2018	TX57J69DDT9R	TX	171918	KS	Truck Tractor	0	1	0
6/21/2018	TX57E90EPWEZ	TX	CHJ2875	TX	Straight Truck	0	1	0
6/18/2018	TX57BC9DILHL	TX	AD95103	TX	Straight Truck	11	1	11
Violation: 396.3A1T Tires (general) (OOS)						8 + 2		
						(OOS)		
Violation: 393.78 Windshield wipers inoperative/defective						1		
Sum of Violation Weight => Inspection Severity Weight (SW)						11		
6/15/2018	TX578F0MUK74	TX	DYK5914	TX	Straight Truck	2	1	2
Violation: 393.9 Inoperable Required Lamp						2		
6/13/2018	TX576E0MUI19	TX	KMB0684	TX	Straight Truck	0	1	0
6/7/2018	TX57099DBBUL	TX	DCF4632	TX	Straight Truck	2	1	2
Violation: 393.9 Inoperable Required Lamp						2		
6/5/2018	TX56YE9DGN10	TX	171918	KS	Truck Tractor	8	1	8
Violation: 393.55(d)(2) CMV manufactured on/after 3/1/2001 not equipped with ABS malfunction circuit / lamp from towed vehicle in cab.						4		
Violation: 393.55(e) No or Defective ABS Malfunction Indicator Lamp for trailer manufactured after 03/01/1998						4		
Sum of Violation Weight => Inspection Severity Weight (SW)						8		
6/1/2018	TX56UE9DLWA7	TX	GFY9977	TX	Straight Truck	8	1	8
Violation: 393.209(c) Loose steering column (OOS)						6 + 2		
						(OOS)		
5/30/2018	TX56S49DKSC4	TX	AP74756	TX	Straight Truck	0	1	0
5/29/2018	TX56R89DILG8	TX	GBH6778	TX	Straight Truck	19	1	19
Violation: 396.17(c) Operating a CMV without proof of a periodic inspection						4		
Violation: 393.95(b) No spare fuses as required						2		
Violation: 393.9 Inoperable Required Lamp						2		
Violation: 393.100(a) No or improper load securement (OOS)						1 + 2		
						(OOS)		
Violation: 393.45(b)(2) Brake hose or tubing chafing and/or kinking (OOS)						4 + 2		
						(OOS)		
Violation: 393.78 Windshield wipers inoperative/defective						1		
Violation: 393.83(g) Exhaust leak under truck cab and/or sleeper						1		
Sum of Violation Weight => Inspection Severity Weight (SW)						19		
5/24/2018	TX56M50MSP55	TX	R121297	TX	Truck Tractor	8	1	8
Violation: 396.17(c) Operating a CMV without proof of a periodic inspection						4		
Violation: 393.45(d) Brake connections with leaks or constrictions						4		
Sum of Violation Weight => Inspection Severity Weight (SW)						8		
5/16/2018	TX56E89DJO6X	TX	GBH6779	TX	Straight Truck	17	1	17
Violation: 396.5(b) Oil and/or grease leak						3		
Violation: 396.3A1T Tires (general) (OOS)						8 + 2		
						(OOS)		
Violation: 393.45(b)(2) Brake hose or tubing chafing and/or kinking						4		
Sum of Violation Weight => Inspection Severity Weight (SW)						17		
5/2/2018	TX560D9DHA2W	TX	AU20656	TX	Straight Truck	15	1	15
Violation: 396.5(b) Oil and/or grease leak						3		
Violation: 393.47(e) Clamp or Roto type brake out-of-adjustment						4		
Violation: 393.45DLUV Brake Connections with Leaks Under Vehicle						4		
Only the 1000 most recent inspections are included in this print view.								
Sum of measure weights						721	194	1,247

Report			Vehicle			Measure =		
						Sum of the Total Weight (TotW)		
						Sum of the Time Weight (TiW)		
Inspection Date	Number	State	Plate Number	Plate State	Type	Severity Weight (SW)	Time Weight (TiW)	Total Weight (TotW)
Violation: 393.53(b) CMV manufactured after 10/19/94 has an automatic airbrake adjustment system that fails to compensate for wear						4		
Sum of Violation Weight => Inspection Severity Weight (SW)						15		
5/1/2018	TX55ZC0XIF2Z	TX	GFY9976	TX	Straight Truck	5	1	5
Violation: 393.9 Inoperable Required Lamp						2		
Violation: 396.5(b) Oil and/or grease leak						3		
Sum of Violation Weight => Inspection Severity Weight (SW)						5		
4/30/2018	TX55Y89DBEOS	TX	CWC2412	TX	Straight Truck	3	1	3
Violation: 392.9 Driver may not operate a CMV without proper load securement (OOS)						1 + 2 (OOS)		
4/27/2018	TX55V79DKK0I	TX	1L13555	TX	Truck Tractor	30***	1	30
Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories						2		
Violation: 393.9TS Inoperative turn signal						6		
Violation: 393.55(d)(3) No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001						4		
Violation: 393.55(d)(1) CMV not equipped with ABS malfunction circuit or signal (Truck-Tractor mfg on/after 3/1/1997; Straight Truck mfg on/after 3/1/1998)						4		
Violation: 393.25(f) Stop lamp violations						6		
Violation: 393.51 No or defective brake warning device						4		
Violation: 396.5B-HLOW Hubs - oil and/or Grease Leaking from hub - outer wheel						2		
Violation: 393.209(e) Power steering violations						6		
Sum of Violation Weight => Inspection Severity Weight (SW)						30***		
4/18/2018	TX55MD9DBO9R	TX	BDK6159	TX	Straight Truck	0	1	0
4/16/2018	TX55K90MSXW0	TX	CJT0753	TX	Truck Tractor	0	1	0
4/11/2018	TX55FA9DBENT	TX	DTP9898	TX	Straight Truck	0	1	0
4/3/2018	TX55799DILDS	TX	R151025	TX	Truck Tractor	30***	1	30
Violation: 393.24(b) Noncompliant fog/driving lamps						6		
Violation: 393.28 Improper or no wiring protection as required						3		
Violation: 393.45(b)(2) Brake hose or tubing chafing and/or kinking (OOS)						4 + 2 (OOS)		
Violation: 393.55(d)(3) No or Defective ABS Malfunction Indicator for towed vehicles on vehicles manufactured after February 2001						4		
Violation: 393.83(g) Exhaust leak under truck cab and/or sleeper						1		
Violation: 393.95(b) No spare fuses as required						2		
Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories						2		
Violation: 393.11TT Truck-Tractor with No retroreflective sheeting or reflex reflective material on vehicle manufactured after July 1997						3		
Violation: 393.45(d) Brake connections with leaks or constrictions						4		
Sum of Violation Weight => Inspection Severity Weight (SW)						30***		
4/2/2018	TX55680SCSOC	TX	AP74756	TX	Straight Truck	0	1	0
3/29/2018	TX55C99DDHA0	TX	1L13595	TX	Truck Tractor	2	1	2
Violation: 396.3(a)(1) Inspection, repair and maintenance of parts & accessories						2		
3/29/2018	TX55289DDT59	TX	BZR8991	TX	Straight Truck	2	1	2
Violation: 393.9 Inoperable Required Lamp						2		
3/22/2018	TX54V89DKWMU	TX	HYS9283	TX	Straight Truck	9	1	9
Violation: 393.47(e) Clamp or Roto type brake out-of-adjustment						4		
Violation: 393.9 Inoperable Required Lamp						2		
Violation: 393.28 Improper or no wiring protection as required						3		
Only the 1000 most recent inspections are included in this print view.								
Sum of measure weights						721	194	1,247

Report			Vehicle			Measure =		
						Sum of the Total Weight (TotW)		
						Sum of the Time Weight (TiW)		
Inspection Date	Number	State	Plate Number	Plate State	Type	Severity Weight (SW)	Time Weight (TiW)	Total Weight (TotW)
Sum of Violation Weight => Inspection Severity Weight (SW)						9		
3/21/2018	TX54U89DGIZ3	TX	AP74758	TX	Straight Truck	3	1	3
Violation: 393.95(a) No/discharged/unsecured fire extinguisher						2		
Violation: 393.78 Windshield wipers inoperative/defective						1		
Sum of Violation Weight => Inspection Severity Weight (SW)						3		
3/6/2018	TX54F80SCSMF	TX	GWH2126	TX	Straight Truck	0	1	0
3/3/2018	TX54CA0VJH20	TX	GSL2773	TX	Straight Truck	6	1	6
Violation: 393.95(b) No spare fuses as required						2		
Violation: 393.9 Inoperable Required Lamp (OOS)						2 + 2 (OOS)		
Sum of Violation Weight => Inspection Severity Weight (SW)						6		
2/5/2018	TX53MA9DLW5Y	TX	BZR9125	TX	Straight Truck	2	1	2
Violation: 393.95(a) No/discharged/unsecured fire extinguisher						2		
2/2/2018	TX53J89DAX3B	TX	BCH0405	TX	Straight Truck	12	1	12
Violation: 396.17(c) Operating a CMV without proof of a periodic inspection						4		
Violation: 393.95(b) No spare fuses as required						2		
Violation: 396.3A1B Brakes (general) Explain:						4		
Violation: 393.9 Inoperable Required Lamp						2		
Sum of Violation Weight => Inspection Severity Weight (SW)						12		
2/2/2018	TX53JF0SCSKF	TX	BC76268	TX	Straight Truck	13	1	13
Violation: 393.75(a)(3) Tire-flat and/or audible air leak (OOS)						8 + 2 (OOS)		
Violation: 396.5(b) Oil and/or grease leak						3		
Sum of Violation Weight => Inspection Severity Weight (SW)						13		
2/1/2018	TX53I80SCSK4	TX	BC76602	TX	Straight Truck	4	1	4
Violation: 393.55(c)(2) CMV other than truck-tractor manufactured on or after March 1, 1998 not equipped with an antilock brake system.						4		
Only the 1000 most recent inspections are included in this print view.								
Sum of measure weights						721	194	1,247

PERFORMANCE MEASURE LAST MONTH As of 12/27/2019	$\frac{\text{TotW}}{\text{TiW}} = \frac{1,254}{194} = 6.46$	PERFORMANCE MEASURE THIS MONTH As of 1/31/2020	$\frac{\text{TotW}}{\text{TiW}} = \frac{1,247}{194} = 6.42$
---	---	--	---

*** The sum of all violation severity weights (violation weight + out-of-service) for this inspection has been capped at 30.

INVESTIGATION RESULTS

Vehicle Maint. Acute/Critical Violations: 0

This carrier has no Vehicle Maintenance Acute/Critical Violations to display.

Summary of Activities

The summary includes information on the 5 most recent investigations

Carrier Registration

Subject to General Threshold

Enforcement Cases

(Six years as of 02/13/2020 updated monthly from [FMCSA](#))

and 24 months of inspections and crash history.

No penalties found

Most Recent Investigation: 7/19/2016
(Non-Ratable Review)

Total Inspections: 127

Total Inspections without
Violations used in SMS: 40

Total Inspections with
Violations used in SMS: 87

Total Crashes* : 9


*Crashes listed represent a motor carrier's involvement in [reportable crashes](#), regardless of the carrier's or driver's role in the crash. [Continue for details](#).


USE OF SMS DATA/INFORMATION

FAST Act of 2015:

Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier has received an UNSATISFACTORY safety rating under part 385 of title 49, Code of Federal Regulations, or has otherwise been ordered to discontinue operations by the Federal Motor Carrier Safety Administration, it is authorized to operate on the Nation's roadways.

Safety Measurement System:

The data in the Safety Measurement System (SMS) is performance data used by the Agency and Enforcement Community. A  symbol, based on that data, indicates that FMCSA may prioritize a motor carrier for further monitoring.

The  symbol is not intended to imply any federal safety rating of the carrier pursuant to 49 USC 31144. Readers should not draw conclusions about a carrier's overall safety condition simply based on the data displayed in this system. Unless a motor carrier in the SMS has received an UNSATISFACTORY safety rating pursuant to 49 CFR Part 385, or has otherwise been ordered to discontinue operations by the FMCSA, it is authorized to operate on the nation's roadways.

Motor carrier safety ratings are available at <http://safer.fmcsa.dot.gov> and motor carrier licensing and insurance status are available at <http://li-public.fmcsa.dot.gov/>.

More Info

On-Road Performance

A carrier's on-road performance in each BASIC is based on 24 months of inspection and crash data.

Performance Measure

Carrier violations or crashes are weighted by time and severity to produce a measure for that carrier in each BASIC. The measure only considers individual performance, with a measure of 0 indicating best performance.

Performance Percentile

The SMS calculates a percentile (based on the measure) for each carrier with sufficient information to be compared against carriers with similar safety events (inspections, inspections with violations, crashes). Percentiles are calculated on a 0–100 scale, with 100 indicating worst performance and 0 indicating best performance.

Intervention Threshold

Intervention Thresholds for carriers are organized by BASIC and are set based on a given BASIC's relationship to crash risk

BASIC	Passenger	HM	General
Vehicle Maintenance	65%	75%	80%

Investigation Results

Acute/Critical Violations

Acute/Critical Violations indicate that a carrier is not complying with federal safety regulations and the carrier must take corrective action.